



# THEODORE HAGANS LEAD WATER TEST RESULTS



	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)
1	THEODORE HAGANS CULTURAL CENTER	WS- 012557	9/22/2016	Ground Floor	Utility	Exterior, adjacent to women's restroom in pool area (water source)	FT-82016-012557-A	< 1	FT-82016-012557-B	< 1
2	THEODORE HAGANS CULTURAL CENTER	WS- 012558	9/22/2016	Ground Floor	Cooler	In lobby adjacent to restrooms High Left	FT-82016-012558-A	< 1	FT-82016-012558-B	< 1
3	THEODORE HAGANS CULTURAL CENTER	WS- 012559	9/22/2016	Ground Floor	Cooler	In lobby adjacent to restrooms Low Right	FT-82016-012559-A	< 1	FT-82016-012559-B	< 1
4	THEODORE HAGANS CULTURAL CENTER	WS- 012560	9/22/2016	Ground Floor	Food Prep Sink	In kitchen	FT-72016-012560-A	< 1	FT-72016-012560-B	< 1