



# VOLTA PARK REC LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 VOLTA PARK RECREATION CENTER	5/20/2016	WS- 012008	Utility	1	In mechanical room (water source)	WT-042916-12025- A	< 2	WT-042916-12025- B	< 2				
2 VOLTA PARK RECREATION CENTER	5/20/2016	WS- 012009	Cooler	1	In main hallway adjacent to office	WT-042916-12026- A	< 2	WT-042916-12026- B	< 2				
3 VOLTA PARK RECREATION CENTER	5/20/2016	WS- 012010	Classroom	2	In north activity room	WT-042916-12027- A	< 2	WT-042916-12027- B	< 2				
4 VOLTA PARK RECREATION CENTER	5/20/2016	WS- 012011	Classroom	2	In south activity room	WT-042916-12028- A	< 2	WT-042916-12028- B	< 2				
5 VOLTA PARK RECREATION CENTER	5/20/2016	WS- 012012	Cooler	Ground Floor	Exterior adjacent to tennis court	WT-042916-12029- A	< 2	WT-042916-12029- B	< 2				
6 VOLTA PARK RECREATION CENTER	5/20/2016	WS- 012013	Cooler	Ground Floor	Exterior adjacent to tennis court	WT-042916-12030- A	< 2	WT-042916-12030- B	< 2				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.