



# YOUTH REHABILITATION LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 YOUTH REHABILITATION BUILDING	5/18/2016	WS- 011472	Utility	Basement	Boiler room (water source)	WT-042916-11489- A	36	WT-042916-11489- B	4.5	Non-drinking water source - Not accessible to children (boilers)			
2 YOUTH REHABILITATION BUILDING	5/18/2016	WS- 011473	Cooler	Basement	In workshop room 0102	WT-042916-11490- A	< 1	WT-042916-11490- B	< 1				
3 YOUTH REHABILITATION BUILDING	5/18/2016	WS- 011514	Cooler	2	In gymnasium	WT-042916-11531- A	< 1	WT-042916-11531- B	< 1				
4 YOUTH REHABILITATION BUILDING	5/18/2016	WS- 011515	Cooler	2	In gymnasium	WT-042916-11532- A	< 1	WT-042916-11532- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.