



AITON ES LEAD WATER TEST RESULTS



	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)
1	AITON ELEMENTARY SCHOOL	WS- 000414	8/17/2016	1	Health Suite	In Health Suite	FT-82016-000414-A	< 1	FT-82016-000414-B	< 1
2	AITON ELEMENTARY SCHOOL	WS- 009509	8/17/2016	1	Food Prep Sink	In kitchen east wall Left	FT-72016-009509-A	< 1	FT-72016-009509-B	< 1
3	AITON ELEMENTARY SCHOOL	WS- 009510	8/17/2016	1	Food Prep Sink	In kitchen east wall Mid	FT-72016-009510-A	< 1	FT-72016-009510-B	< 1
4	AITON ELEMENTARY SCHOOL	WS- 009512	8/17/2016	1	Cooler	In hallway in lobby	FT-72016-009512-A	< 1	FT-72016-009512-B	< 1
5	AITON ELEMENTARY SCHOOL	WS- 009514	8/17/2016	1	Cooler	In hallway across from health suite	FT-72016-009514-A	< 1	FT-72016-009514-B	< 1
6	AITON ELEMENTARY SCHOOL	WS- 009515	8/17/2016	1	Cooler	In classroom K-1	FT-72016-009515-A	< 1	FT-72016-009515-B	< 1
7	AITON ELEMENTARY SCHOOL	WS- 009518	8/17/2016	1	Cooler	In classroom K-2	FT-72016-009518-A	< 1	FT-72016-009518-B	< 1
8	AITON ELEMENTARY SCHOOL	WS- 009519	8/17/2016	2	Cooler	In hallway adjacent to room 203	FT-82016-009519-A	< 1	FT-82016-009519-B	< 1
9	AITON ELEMENTARY SCHOOL	WS- 009521	8/17/2016	2	Cooler	In hallway adjacent to library	FT-82016-009521-A	< 1	FT-82016-009521-B	< 1
10	AITON ELEMENTARY SCHOOL	WS- 009522	8/17/2016	3	Cooler	In hallway adjacent to room 301	FT-82016-009522-A	< 1	FT-82016-009522-B	< 1
11	AITON ELEMENTARY SCHOOL	WS- 009523	8/17/2016	3	Cooler	In hallway adjacent to room 305	FT-82016-009523-A	< 1	FT-82016-009523-B	< 1
12	AITON ELEMENTARY SCHOOL	WS- 009528	8/17/2016	4	Cooler	In hallway adjacent to room 401	FT-72016-009528-A	< 1	FT-72016-009528-B	< 1
13	AITON ELEMENTARY SCHOOL	WS- 009529	8/17/2016	4	Cooler	In hallway adjacent to room 406	FT-72016-009529-A	< 1	FT-72016-009529-B	< 1