



AITON LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009508	Utility	1	In boiler room	WT-042916-9525- A	1.3	WT-042916-9525- B	< 1				
2 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009509	Kitchen	1	In kitchen east wall sink Left	WT-042916-9526- A	< 1	WT-042916-9526- B	< 1				
3 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009510	Kitchen	1	In kitchen east wall sink Mid	WT-042916-9527- A	< 1	WT-042916-9527- B	< 1				
4 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009511	Kitchen	1	In kitchen east wall sink Right	WT-042916-9528- A	1.5	WT-042916-9528- B	1.6				
5 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009512	Cooler	1	In hallway lobby	WT-042916-9529- A	< 1	WT-042916-9529- B	< 1				
6 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009513	Health Suite	1	In health suite sink	WT-042916-9530- A	41.7	WT-042916-9530- B	< 1	Filter will be installed and then retested			
7 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009514	Cooler	1	In hallway across from health suite	WT-042916-9531- A	< 1	WT-042916-9531- B	< 1				
8 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009515	Cooler	1	In room K-1	WT-042916-9532- A	< 1	WT-042916-9532- B	< 1				
9 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009516	Classroom	1	In classroom k1 Right	WT-042916-9533- A	< 1	WT-042916-9533- B	< 1				
10 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009517	Classroom	1	In classroom k2 Left	WT-042916-9534- A	1.1	WT-042916-9534- B	< 1				
11 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009518	Cooler	1	In room K-2	WT-042916-9535- A	< 1	WT-042916-9535- B	< 1				
12 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009519	Cooler	2	In hallway adjacent to room 203	WT-042916-9536- A	1.2	WT-042916-9536- B	1.1				
13 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009520	Break Room	2	In break room sink	WT-042916-9537- A	< 1	WT-042916-9537- B	< 1				
14 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009521	Cooler	2	In hallway adjacent to library	WT-042916-9538- A	< 1	WT-042916-9538- B	< 1				
15 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009522	Cooler	3	In hallway adjacent to room 301	WT-042916-9539- A	< 1	WT-042916-9539- B	< 1				
16 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009523	Cooler	3	In hallway adjacent to room 305	WT-042916-9540- A	< 1	WT-042916-9540- B	< 1				
17 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009524	Classroom	3	In room 301	WT-042916-9541- A	4.2	WT-042916-9541- B	< 1				
18 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009525	Classroom	3	In room 301	WT-042916-9542- A	3.6	WT-042916-9542- B	< 1				
19 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009526	Classroom	4	In room 401	WT-042916-9543- A	2.4	WT-042916-9543- B	3.1				
20 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009527	Classroom	4	In classroom 401 Left	WT-042916-9544- A	39	WT-042916-9544- B	1.2	Filter will be installed and then retested			
21 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009528	Cooler	4	In hallway adjacent to room 401	WT-042916-9545- A	< 1	WT-042916-9545- B	< 1				
22 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009529	Cooler	4	In hallway adjacent to room 406	WT-042916-9546- A	< 1	WT-042916-9546- B	< 1				
23 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009530	Classroom	3	In classroom 302	WT-042916-9547- A	< 1	WT-042916-9547- B	< 1				
24 AITON ELEMENTARY SCHOOL	5/10/2016	WS-009531	Classroom	3	In classroom 302 Right	WT-042916-9548- A	18.5	WT-042916-9548- B	4.3	Filter will be installed and then retested			

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.