



# ANACOSTIA REC LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	ANACOSTIA RECREATION CENTER	5/19/2016	WS- 005330	Cooler	1	In hallway	WT-042916-5347- A	1.7	WT-042916-5347- B	< 1				
2	ANACOSTIA RECREATION CENTER	5/19/2016	WS- 005331	Kitchen	1	In left gym	WT-042916-5348- A	4.1	WT-042916-5348- B	8.8				
1	ANACOSTIA RECREATION CENTER	5/19/2016	WS- 005332	Utility	Basement	Pool mechanical room (water source)	WT-042916-5349- A	< 1	WT-042916-5349- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.