

COMPANY NAME

COMPANY ADDRESS

COMPANY POINT OF CONTRACT

POINT OF CONTACT PHONE NUMBER /EMAIL ADDRESS

Contract Number:

Purchase Order Number:

Inspection Date:

Inspector:

Name, email/phone number...

INSPECTION LOCATION

Brightwood Elementary School - 00D5226704
1300 Nicholson Street NW
Washington, DC 20011
Location Phone Number

CUSTOMER

Brightwood Elementary School - 00D5226704
1300 Nicholson Street NW
Washington, DC 20011
Location Phone Number

All inspection performed in accordance with NFPA 25
Standard for the Inspection, Testing and Maintenance of Water-Based Fire Protection Systems, 2017 edition.

Control Value								
Type	Area/Location	Valve Size	Accessible	Condition	Secured	Exercised Seal	Value Test	
Control Valve-loc 1st Floor Stair A		Butterfly 4"	Pass	Pass	Pass	TAG	PASS	
Control Valve-loc 1st Floor Stair A		Butterfly 4"	Pass	Pass	Pass	TAG	PASS	
Control Valve-loc 1st Floor Stair B		OS and Y 4"	Pass	Pass	Pass	TAG	PASS	
Control Valve-loc 3st Floor Stair 3		Butterfly 4"	Pass	Pass	Pass	TAG	PASS	
Control Valve-loc 2st Floor Stair B		Butterfly 6"	Pass	Pass	Pass	TAG	PASS	
Control Valve-loc Backflow Basement		OS and Y 4"	Pass	Pass	Pass	TAG	PASS	
Control Valve-loc Backflow Basement		OS and Y 6"	Pass	Pass	Pass	TAG	PASS	
Control Valve-loc Boiler Room/ Basement			Pass	Pass	Pass	TAG	PASS	

Alarm Devices			
Type	Area/Location	Visual Insp	Functional Test
Waterflow Alarm 1st Floor Stair A		Pass	Pass
Waterflow Press. 1st Floor Stair B		Pass	N/I
Waterflow - Alarr 2nd Floor Stair A		Pass	Pass
Waterflow - Alarr 2nd Floor Stair B		Pass	Pass
Waterflow Press. 3st Floor Stair A		Pass	N/I
Waterflow Press. Basement Boiler Room		Pass	Pass
Waterflow Press. Basement Hall		Pass	N/I

Deficiencies

Pictures

Pictures

Pictures

Pictures

Pictures

Not Inspected	
Waterflow - Pressure Switch	
1st Floor Stair B	

Liability Release Statement:

Date:

Date:

Customer:
Signature

Tech:
Signature