

COMPANY NAME

COMPANY ADDRESS

COMPANY POINT OF CONTRACT

POINT OF CONTACT PHONE NUMBER /EMAIL ADDRESS

Contract Number:

Purchase Order Number:

Inspection Date:

Inspector:

Name, email/phone number...

INSPECTION LOCATION

Brightwood Elementary School - 00D5226704

1300 Nicholson Street NW

Washington, DC 20011

Location Phone Number

CUSTOMER

Brightwood Elementary School - 00D5226704

1300 Nicholson Street NW

Washington, DC 20011

Location Phone Number

All inspections performed in accordance with NFPA 25
Standard for the Inspection, Testing and Maintenance of Water-Based Fire Protection Systems, 2017 edition.

Control Value

Type	Area/Location	Label Size	Accessible	Condition	Secured	Exercised Seal	Value Test
Control Valve-loc	1st Floor Stair A	Butterfly 4"	Pass	Pass	Pass	TAG	PASS
Control Valve-loc	1st Floor Stair A	Butterfly	Pass	Pass	Pass	TAG	PASS
Control Valve-loc	1st Floor Stair B	OS and Y 4"	Pass	Pass	Pass	TAG	PASS
Control Valve-loc	3rd Floor Stair 3	Butterfly 4"	Pass	Pass	Pass	TAG	PASS
Control Valve-loc	2nd Floor Stair B	Butterfly 6"	Pass	Pass	Pass	TAG	PASS
Control Valve-loc	Backflow Basement	OS and Y 4"	Pass	Pass	Pass	TAG	PASS
Control Valve-loc	Backflow Basement	OS and Y 6"	Pass	Pass	Pass	TAG	PASS
Control Valve-loc	Boiler Room / Basement		Pass	Pass	Pass	TAG	PASS

Alarm Devices

Type	Area/Location	Visual Insp	Functional Test
Waterflow Alarm	1st Floor Stair A	Pass	Pass
Waterflow Press	1st Floor Stair B	Pass	N/I
Waterflow - Alarr	2nd Floor Stair A	Pass	Pass
Waterflow - Alarr	2nd Floor Stair B	Pass	Pass
Waterflow Press	3rd Floor Stair A	Pass	N/I
Waterflow Press	Basement Boiler Room	Pass	Pass
Waterflow Press	Basement Hall	Pass	N/I

Deficiencies

Pictures

Pictures

Pictures

Pictures

Pictures

Not Inspected

Waterflow - Pressure Switch

1st Floor Stair B

Liability Release Statement:

Date:

Date:

Customer:
Signature

Tech:
Signature