



Bald Eagle RC Lead in Water Test Results

FY26 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012587	2/23/2026	2/23/2027	Ground Floor	Cooler	In hallway across from men's and women's room (filter in ceiling) High Left	WF-02232026-012587	4/9/2026	FT-FY26-03262026-012587-A	<2	FT-FY26-03262026-012587-B	<2
WS- 012588	2/23/2026	2/23/2027	Ground Floor	Cooler	In hallway across from men's and women's room Low Right	WF-02232026-012588	4/9/2026	FT-FY26-03262026-012588-A	<2	FT-FY26-03262026-012588-B	<2
WS- 012589	2/23/2026	2/23/2027	Ground Floor	Cooler	In hallway across from fitness room 212 Low Left	WF-02232026-012589	4/9/2026	FT-FY26-03262026-012589-A	<2	FT-FY26-03262026-012589-B	<2
WS- 012590	2/23/2026	2/23/2027	Ground Floor	Cooler	In hallway across from fitness room 212 High Right	WF-02232026-012590	4/9/2026	FT-FY26-03262026-012590-A	<2	FT-FY26-03262026-012590-B	<2
WS- 012591	11/24/2025	11/24/2026	Ground Floor	Food Prep Sink	In kitchen 101 north wall	WF-11242025-012591	4/9/2026	FT-FY26-03262026-012591-A	<2	FT-FY26-03262026-012591-B	<2
WS- 012593	11/24/2025	11/24/2026	Ground Floor	Food Prep Sink	In pantry room 216 north wall	WF-11242025-012593	4/9/2026	FT-FY26-03262026-012593-A	<2	FT-FY26-03262026-012593-B	<2
WS- 012595	2/23/2026	2/23/2027	Ground Floor	Cooler	In boxing annex on east wall Low Right	WF-02232026-012595	4/9/2026	FT-FY26-03262026-012595-A	<2	FT-FY26-03262026-012595-B	<2
WS- 012596	2/23/2026	2/23/2027	Ground Floor	Cooler	In boxing annex on east wall High Left	WF-02232026-012596	4/9/2026	FT-FY26-03262026-012596-A	<2	FT-FY26-03262026-012596-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.