



Bald Eagle RC Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012587	4/5/2019	4/5/2020	Ground Floor	Cooler	In hallway across from men's and women's room	High Left	WF-04052019-012587	3/18/2020	FT-FY20-012020-012587-A	<1	FT-FY20-012020-012587-B	<1
WS- 012588	4/5/2019	4/5/2020	Ground Floor	Cooler	In hallway across from men's and women's room	Low Right	WF-04052019-012588	3/18/2020	FT-FY20-012020-012588-A	<1	FT-FY20-012020-012588-B	<1
WS- 012589	4/4/2019	4/4/2020	Ground Floor	Cooler	In hallway across from fitness room 212	Low Left	WF-04042019-012589	3/18/2020	FT-FY20-012020-012589-A	<1	FT-FY20-012020-012589-B	<1
WS- 012590	4/4/2019	4/4/2020	Ground Floor	Cooler	In hallway across from fitness room 212	High Right	WF-04042019-012590	3/18/2020	FT-FY20-012020-012590-A	<1	FT-FY20-012020-012590-B	<1
WS- 012591	4/4/2019	4/4/2020	Ground Floor	Food Prep Sink	In kitchen 101 north wall		WF-04042019-012591	3/18/2020	FT-FY20-012020-012591-A	<1	FT-FY20-012020-012591-B	<1
WS- 012593	4/4/2019	4/4/2020	Ground Floor	Food Prep Sink	In pantry room 216 north wall		WF-04042019-012593	3/18/2020	FT-FY20-012020-012593-A	<1	FT-FY20-012020-012593-B	<1
WS- 012595	4/4/2019	4/4/2020	Ground Floor	Cooler	In boxing annex on east wall	Low Right	WF-04042019-012595	3/18/2020	FT-FY20-012020-012595-A	<1	FT-FY20-012020-012595-B	<1
WS- 012596	4/4/2019	4/4/2020	Ground Floor	Cooler	In boxing annex on east wall	High Left	WF-04042019-012596	3/18/2020	FT-FY20-012020-012596-A	<1	FT-FY20-012020-012596-B	<1