



Bald Eagle Recreation Center Lead in Water Test Results

FY23 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012587	3/21/2022	3/21/2023	Ground Floor	Cooler	In hallway across from men's and women's room (filter in ceiling) High Left	WF-03212022-012587	3/8/2023	FT-FY23-02022023-012587-A	<1	FT-FY23-02022023-012587-B	<1
WS- 012588	3/21/2022	3/21/2023	Ground Floor	Cooler	In hallway across from men's and women's room Low Right	WF-03212022-012588	3/8/2023	FT-FY23-02022023-012588-A	<1	FT-FY23-02022023-012588-B	<1
WS- 012589	3/21/2022	3/21/2023	Ground Floor	Cooler	In hallway across from fitness room 212 Low Left	WF-03212022-012589	3/8/2023	FT-FY23-02022023-012589-A	<1	FT-FY23-02022023-012589-B	<1
WS- 012590	3/21/2022	3/21/2023	Ground Floor	Cooler	In hallway across from fitness room 212 High Right	WF-03212022-012590	3/8/2023	FT-FY23-02022023-012590-A	<1	FT-FY23-02022023-012590-B	<1
WS- 012591	1/10/2023	1/10/2024	Ground Floor	Food Prep Sink	In kitchen 101 north wall	WF-01102023-012591	3/8/2023	FT-FY23-02022023-012591-A	<1	FT-FY23-02022023-012591-B	1.6
WS- 012593	1/10/2023	1/10/2024	Ground Floor	Food Prep Sink	In pantry room 216 north wall	WF-01102023-012593	3/8/2023	FT-FY23-02022023-012593-A	<1	FT-FY23-02022023-012593-B	3.4
WS- 012595	3/21/2022	3/21/2023	Ground Floor	Cooler	In boxing annex on east wall Low Right	WF-03212022-012595	3/8/2023	FT-FY23-02022023-012595-A	<1	FT-FY23-02022023-012595-B	<1
WS- 012596	3/21/2022	3/21/2023	Ground Floor	Cooler	In boxing annex on east wall High Left	WF-03212022-012596	3/8/2023	FT-FY23-02022023-012596-A	<1	FT-FY23-02022023-012596-B	<1