



Bald Eagle Recreation Center Lead in Water Test Results

FY24 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012587	3/4/2024	3/4/2025	Ground Floor	Cooler	In hallway across from men's and women's room	High Left	WF-03042024-012587	3/26/2024	FT-FY24-03112024-012587-A	<1	FT-FY24-03112024-012587-B	<1
WS- 012588	3/4/2024	3/4/2025	Ground Floor	Cooler	In hallway across from men's and women's room	Low Right	WF-03042024-012588	3/26/2024	FT-FY24-03112024-012588-A	<1	FT-FY24-03112024-012588-B	<1
WS- 012589	3/4/2024	3/4/2025	Ground Floor	Cooler	In hallway across from fitness room 212	Low Left	WF-03042024-012589	3/26/2024	FT-FY24-03112024-012589-A	<1	FT-FY24-03112024-012589-B	<1
WS- 012590	3/4/2024	3/4/2025	Ground Floor	Cooler	In hallway across from fitness room 212	High Right	WF-03042024-012590	3/26/2024	FT-FY24-03112024-012590-A	<1	FT-FY24-03112024-012590-B	<1
WS- 012591	12/5/2023	12/5/2024	Ground Floor	Food Prep Sink	In kitchen 101 north wall		WF-12052023-012591	3/26/2024	FT-FY24-03112024-012591-A	<1	FT-FY24-03112024-012591-B	<1
WS- 012593	12/5/2023	12/5/2024	Ground Floor	Food Prep Sink	In pantry room 216 north wall		WF-12052023-012593	3/26/2024	FT-FY24-03112024-012593-A	<1	FT-FY24-03112024-012593-B	<1
WS- 012595	3/4/2024	3/4/2025	Ground Floor	Cooler	In boxing annex on east wall	Low Right	WF-03042024-012595	3/26/2024	FT-FY24-03112024-012595-A	<1	FT-FY24-03112024-012595-B	<1
WS- 012596	3/4/2024	3/4/2025	Ground Floor	Cooler	In boxing annex on east wall	High Left	WF-03042024-012596	3/26/2024	FT-FY24-03112024-012596-A	<1	FT-FY24-03112024-012596-B	<1