



# Bald Eagle Lead in Water Test Results

## FY21 Filter Test

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012587	4/4/2020	4/4/2021	Ground Floor	Cooler	In hallway across from men's and women's room	High	Left	WF-04042020-012587	4/1/2021	FT-FY21-032021-012587-A	<1	FT-FY21-032021-012587-B	<1
WS- 012588	4/4/2020	4/4/2021	Ground Floor	Cooler	In hallway across from men's and women's room	Low	Right	WF-04042020-012588	4/1/2021	FT-FY21-032021-012588-A	<1	FT-FY21-032021-012588-B	<1
WS- 012589	4/4/2020	4/4/2021	Ground Floor	Cooler	In hallway across from fitness room 212	Low	Left	WF-04042020-012589	4/1/2021	FT-FY21-032021-012589-A	<1	FT-FY21-032021-012589-B	<1
WS- 012595	4/4/2020	4/4/2021	Ground Floor	Cooler	In boxing annex on east wall	Low	Right	WF-04042020-012595	4/1/2021	FT-FY21-032021-012595-A	<1	FT-FY21-032021-012595-B	<1
WS- 012596	4/4/2020	4/4/2021	Ground Floor	Cooler	In boxing annex on east wall	High	Left	WF-04042020-012596	4/1/2021	FT-FY21-032021-012596-A	<1	FT-FY21-032021-012596-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012591	2/9/2021	2/9/2022	Ground Floor	Food Prep Sink	In kitchen 101 north wall			WF-02092021-012591	4/1/2021	FT-FY21-032021-012591-A	<1	FT-FY21-032021-012591-B	<1
WS- 012593	2/9/2021	2/9/2022	Ground Floor	Food Prep Sink	In pantry room 216 north wall			WF-02092021-012593	4/1/2021	FT-FY21-032021-012593-A	<1	FT-FY21-032021-012593-B	<1