



Bald Eagle Lead in Water Test Results

FY22 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-012587	3/22/2021	3/22/2022	Ground Floor	Cooler	In hallway across from men's and women's room (filter in ceiling) High Left	WF-03222021-012587	3/19/2022	FT-FY22-02212022-012587-A	<1	FT-FY22-02212022-012587-B	<1
WS-012588	3/22/2021	3/22/2022	Ground Floor	Cooler	In hallway across from men's and women's room Low Right	WF-03222021-012588	3/19/2022	FT-FY22-02212022-012588-A	1.0	FT-FY22-02212022-012588-B	<1
WS-012590	3/22/2021	3/22/2022	Ground Floor	Cooler	In hallway across from fitness room 212 High Right	WF-03222021-012590	3/19/2022	FT-FY22-02212022-012590-A	<1	FT-FY22-02212022-012590-B	<1
WS-012591	2/7/2022	2/7/2023	Ground Floor	Food Prep Sink	In kitchen 101 north wall	WF-02072022-012591	3/19/2022	FT-FY22-02212022-012591-A	2.2	FT-FY22-02212022-012591-B	3.3
WS-012593	2/7/2022	2/7/2023	Ground Floor	Food Prep Sink	In pantry room 216 north wall	WF-02072022-012593	3/19/2022	FT-FY22-02212022-012593-A	<1	FT-FY22-02212022-012593-B	<1
WS-012595	3/22/2021	3/22/2022	Ground Floor	Cooler	In boxing annex on east wall Low Right	WF-03222021-012595	3/19/2022	FT-FY22-02212022-012595-A	<1	FT-FY22-02212022-012595-B	<1
WS-012596	3/22/2021	3/22/2022	Ground Floor	Cooler	In boxing annex on east wall High Left	WF-03222021-012596	3/19/2022	FT-FY22-02212022-012596-A	<1	FT-FY22-02212022-012596-B	<1