



BALD EAGLE LEAD WATER TEST RESULTS



Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)
1 BALD EAGLE	WS- 012587	9/21/2016	Ground Floor	Cooler	In hallway across from men's and women's room High Left	FT-92016-012587-A	< 1	FT-92016-012587-B	< 1
2 BALD EAGLE	WS- 012588	9/21/2016	Ground Floor	Cooler	In hallway across from men's and women's room Low Right	FT-82016-012588-A	< 1	FT-82016-012588-B	< 1
3 BALD EAGLE	WS- 012589	9/21/2016	Ground Floor	Cooler	In hallway across from fitness room 212 Low	FT-82016-012589-A	< 1	FT-82016-012589-B	< 1
4 BALD EAGLE	WS- 012590	9/21/2016	Ground Floor	Cooler	In hallway across from fitness room 212 High	FT-82016-012590-A	< 1	FT-82016-012590-B	< 1
5 BALD EAGLE	WS- 012591	9/21/2016	Ground Floor	Food Prep Sink	In kitchen 101 north wall	FT-82016-012591-A	< 1	FT-82016-012591-B	< 1
6 BALD EAGLE	WS- 012593	9/21/2016	Ground Floor	Food Prep Sink	In pantry room 213 north wall	FT-82016-012593-A	< 1	FT-82016-012593-B	< 1
7 BALD EAGLE	WS- 012594	9/21/2016	Ground Floor	Sprayer	In pantry room 213 north wall (spray nozzle)	FT-82016-012594-A	< 1	FT-82016-012594-B	< 1
8 BALD EAGLE	WS- 012595	9/21/2016	Ground Floor	Cooler	In boxing annex on east wall Low Right	FT-82016-012595-A	< 1	FT-82016-012595-B	< 1
9 BALD EAGLE	WS- 012596	9/21/2016	Ground Floor	Cooler	In boxing annex on east wall High Left	FT-82016-012596-A	< 1	FT-82016-012596-B	< 1