



Banneker CC Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-012667	5/12/2018	5/12/2019	1	Cooler	In hallway adjacent to room 102 in lobby High Left	WF-05122018-012667	2/4/2019	FT-FY19-012019-012667-A	<1	FT-FY19-012019-012667-B	<1
WS-012668	5/12/2018	5/12/2019	1	Cooler	In hallway adjacent to room 102 in lobby Low Right	WF-05122018-012668	2/4/2019	FT-FY19-012019-012668-A	<1	FT-FY19-012019-012668-B	<1
WS-012669	5/12/2018	5/12/2019	1	Bottle Filler	In hallway adjacent to room 102 in lobby	WF-05122018-012669	2/4/2019	FT-FY19-012019-012669-A	<1	FT-FY19-012019-012669-B	<1
WS-012670	5/12/2018	5/12/2019	Basement	Cooler	In hallway adjacent to men's locker room High Left	WF-05122018-012670	2/4/2019	FT-FY19-012019-012670-A	<1	FT-FY19-012019-012670-B	<1
WS-012671	5/12/2018	5/12/2019	Basement	Cooler	In hallway adjacent to men's locker room Low Right	WF-05122018-012671	2/4/2019	FT-FY19-012019-012671-A	<1	FT-FY19-012019-012671-B	<1
WS-012672	5/12/2018	5/12/2019	Basement	Bottle Filler	In hallway adjacent to men's locker room	WF-05122018-012672	2/4/2019	FT-FY19-012019-012672-A	<1	FT-FY19-012019-012672-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-012655	5/12/2018	5/12/2019	1	Food Prep Sink	In kitchenette in gym	WF-05122018-012655	2/4/2019	FT-FY19-012019-012655-A	<1	FT-FY19-012019-012655-B	<1