



# Barry Farm RC Lead Water Test Results



## FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation													
RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-006115	6/23/17	6/23/18	1	Cooler	In pool area	Right		WF-62017-006115	3/1/18	FT-FY18--62017-006115-A	<1	FT-FY18--62017-006115-B	<1
WS-006121	6/23/17	6/23/18	1	Cooler	In hallway adjacent to gym entrance	Left	High	WF-62017-006121	3/1/18	FT-FY18--62017-006121-A	<1	FT-FY18--62017-006121-B	<1
WS-006122	6/23/17	6/23/18	1	Cooler	In hallway adjacent to gym entrance	Right	Low	WF-62017-006122	3/1/18	FT-FY18--62017-006122-A	<1	FT-FY18--62017-006122-B	<1

## Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation													
RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-006112	6/23/17	6/23/18	1	Food Prep Sink	In kitchen	Left		WF-62017-006112	3/1/18	FT-FY18--62017-006112-A	<1	FT-FY18--62017-006112-B	<1
WS-006113	6/23/17	6/23/18	1	Food Prep Sink	In kitchen	Right		WF-62017-006113	3/1/18	FT-FY18--62017-006113-A	<1	FT-FY18--62017-006113-B	<1