



Barry Farm RC Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 006112	4/18/2019	4/18/2020	1	Food Prep Sink	In kitchen	Left	WF-04182019-006112	3/18/2020	FT-FY20-012020-006112-A	<1	FT-FY20-012020-006112-B	<1
WS- 006113	4/18/2019	4/18/2020	1	Food Prep Sink	In kitchen	Right	WF-04182019-006113	3/18/2020	FT-FY20-012020-006113-A	<1	FT-FY20-012020-006113-B	<1
WS- 006114	4/18/2019	4/18/2020	1	Cooler	In pool area	High Left	WF-04182019-006114	3/18/2020	FT-FY20-012020-006114-A	<1	FT-FY20-012020-006114-B	<1
WS- 006115	4/18/2019	4/18/2020	1	Cooler	In pool area	Right	WF-04182019-006115	3/18/2020	FT-FY20-012020-006115-A	<1	FT-FY20-012020-006115-B	<1
WS- 006116	4/18/2019	4/18/2020	1	Break Room	In seniors' lounge		WF-04182019-006116	3/18/2020	FT-FY20-012020-006116-A	<1	FT-FY20-012020-006116-B	<1
WS- 006118	4/18/2019	4/18/2020	1	Cooler	In hallway adjacent to seniors' lounge	High Left	WF-04182019-006118	3/18/2020	FT-FY20-012020-006118-A	<1	FT-FY20-012020-006118-B	<1
WS- 006119	4/18/2019	4/18/2020	1	Cooler	In hallway adjacent to seniors' lounge	Low Right	WF-04182019-006119	3/18/2020	FT-FY20-012020-006119-A	<1	FT-FY20-012020-006119-B	<1
WS- 006121	4/18/2019	4/18/2020	1	Cooler	In hallway adjacent to gym entrance	High Left	WF-04182019-006121	3/18/2020	FT-FY20-012020-006121-A	<1	FT-FY20-012020-006121-B	<1
WS- 006122	4/18/2019	4/18/2020	1	Cooler	In hallway adjacent to gym entrance	Low Right	WF-04182019-006122	3/18/2020	FT-FY20-012020-006122-A	<1	FT-FY20-012020-006122-B	<1