



# BARRY FARM REC LEAD WATER TEST RESULTS May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006111	Other	1	In indoor pool area spigot (water source)	WT-042916-6128- A	< 1	WT-042916-6128- B	< 1				
2	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006112	Kitchen	1	In kitchen Left	WT-042916-6129- A	< 1	WT-042916-6129- B	< 1				
3	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006113	Kitchen	1	In kitchen Right	WT-042916-6130- A	< 1	WT-042916-6130- B	< 1				
4	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006114	Cooler	1	In indoor pool area Left High	WT-042916-6131- A	< 1	WT-042916-6131- B	< 1				
5	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006115	Cooler	1	In indoor pool area Right	WT-042916-6132- A	< 1	WT-042916-6132- B	< 1				
6	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006116	Break Room	1	In senior's lounge room	WT-042916-6133- A	< 1	WT-042916-6133- B	< 1				
7	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006117	Other	1	In senior's lounge (ice maker/water cooler fridge)	WT-042916-6134- A	< 1	WT-042916-6134- B	< 1				
8	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006118	Cooler	1	In hallway adjacent to senior's lounge room Left High	WT-042916-6135- A	< 1	WT-042916-6135- B	< 1				
9	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006119	Cooler	1	In hallway adjacent to senior's lounge room Right Low	WT-042916-6136- A	< 1	WT-042916-6136- B	< 1				
10	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006120	Classroom	1	In arts and crafts room	WT-042916-6137- A	< 1	WT-042916-6137- B	< 1				
11	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006121	Cooler	1	In hallway adjacent to gym entrance near man's restroom Left High	WT-042916-6138- A	< 1	WT-042916-6138- B	< 1				
12	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006122	Cooler	1	In hallway adjacent to gym entrance near man's restroom Right Low	WT-042916-6139- A	< 1	WT-042916-6139- B	< 1				
13	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006123	Fountain	1	Exterior adjacent to basketball field - east side Right High	WT-042916-6140- A	< 1	WT-042916-6140- B	< 1				
14	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006124	Fountain	1	Exterior adjacent to basketball field - east side Left Low	WT-042916-6141- A	< 1	WT-042916-6141- B	< 1				
15	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006125	Fountain	1	Exterior adjacent to basketball field - west side Right High	WT-042916-6142- A	< 1	WT-042916-6142- B	< 1				
16	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006126	Fountain	1	Exterior adjacent to basketball field - west side Left Low	WT-042916-6143- A	< 1	WT-042916-6143- B	< 1				
17	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006127	Fountain	1	Exterior near back face of building adjacent to soccer field - east side Right High	WT-042916-6144- A	< 1	WT-042916-6144- B	< 1				
18	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006128	Fountain	1	Exterior near back face of building adjacent to soccer field - east side Left Low	WT-042916-6145- A	< 1	WT-042916-6145- B	< 1				
19	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006129	Fountain	1	Exterior near back face of building adjacent to soccer field - west side Right High	WT-042916-6146- A	< 1	WT-042916-6146- B	< 1				
20	BARRY FARM RECREATION CENTER	5/21/2016	WS- 006130	Fountain	1	Exterior near back face of building adjacent to soccer field - west side Left Low	WT-042916-6147- A	< 1	WT-042916-6147- B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.