



# Benning Park RC Lead Water Test Results



## FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 003786	6/13/17	6/13/18	1	Cooler	In hallway adjacent to custodian's room	WF-62017-003786	2/21/18	FT-FY18--62017-003786-A	<1	FT-FY18--62017-003786-B	<1

## Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 003785	6/13/17	6/13/18	1	Food Prep Sink	In kitchen	WF-62017-003785	2/21/18	FT-FY18--62017-003785-A	<1	FT-FY18--62017-003785-B	<1