



# Benning Park Rec Lead in Water Test Results



## FY20 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 003779	4/1/2019	4/1/2020	1	Cooler	In hallway adjacent to staff room	WF-04012019-003779	3/12/2020	FT-FY20-012020-003779-A	<1	FT-FY20-012020-003779-B	<1
WS- 003785	4/1/2019	4/1/2020	1	Food Prep Sink	In kitchen	WF-04012019-003785	3/12/2020	FT-FY20-012020-003785-A	<1	FT-FY20-012020-003785-B	<1
WS- 003786	4/1/2019	4/1/2020	1	Cooler	In hallway adjacent to custodian's room	WF-04012019-003786	3/12/2020	FT-FY20-012020-003786-A	<1	FT-FY20-012020-003786-B	<1