



BENNING PARK LEAD WATER TEST RESULTS



	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)
1	BENNING PARK REC	WS- 003779	9/20/2016	1	Cooler	In hallway adjacent to staff room	FT-82016-003779-A	< 1	FT-82016-003779-B	< 1
2	BENNING PARK REC	WS- 003785	9/20/2016	1	Food Prep Sink	In kitchen	FT-82016-003785-A	< 1	FT-82016-003785-B	< 1
3	BENNING PARK REC	WS- 003786	9/20/2016	1	Cooler	In hallway adjacent to custodian's room	FT-82016-003786-A	< 1	FT-82016-003786-B	< 1