



# Benning Stoddert RC Lead in Water Test Results

## FY21 Filter Test

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 001030	3/29/2021	3/29/2022	Ground Floor	Cooler	In hallway adjacent to restrooms	High	Left	WF-03292021-001030	4/13/2021	FT-FY21-042021-001030-A	<1	FT-FY21-042021-001030-B	<1
WS- 001031	3/29/2021	3/29/2022	Ground Floor	Cooler	In hallway adjacent to restrooms	Low	Right	WF-03292021-001031	4/13/2021	FT-FY21-042021-001031-A	<1	FT-FY21-042021-001031-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 001028	1/15/2021	1/15/2022	Ground Floor	Food Prep Sink	In kitchen adjacent to room 110			WF-01152021-001028	4/12/2021	FT-FY21-042021-001028-A	<1	FT-FY21-042021-001028-B	<1