



# Benning Stoddert Recreation Center Lead in Water Test Results

## FY24 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 001028	11/20/2023	11/20/2024	Ground Floor	Food Prep Sink	In kitchen adjacent to room 110	WF-11202023-001028	4/1/2024	FT-FY24-03202024-001028-A	<1	FT-FY24-03202024-001028-B	<1
WS- 001030	3/11/2024	3/11/2025	Ground Floor	Cooler	In hallway adjacent to restrooms High Left	WF-03112024-001030	4/1/2024	FT-FY24-03202024-001030-A	<1	FT-FY24-03202024-001030-B	<1
WS- 001031	3/11/2024	3/11/2025	Ground Floor	Cooler	In hallway adjacent to restrooms Low Right	WF-03112024-001031	4/1/2024	FT-FY24-03202024-001031-A	<1	FT-FY24-03202024-001031-B	<1
WS- 001032	3/11/2024	3/11/2025	Ground Floor	Bottle Filler	In hallway adjacent to restrooms	WF-03112024-001032	4/1/2024	FT-FY24-03202024-001032-A	<1	FT-FY24-03202024-001032-B	<1