



Benning Stoddert RC Lead Water Test Results **elev★te**

FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation											
RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 001030	9/11/17	9/11/18	Ground Floor	Cooler	In hallway adjacent to restrooms Left High	WF-92017-001030	2/21/18	FT-FY18--92017-001030-A	<1	FT-FY18--92017-001030-B	<1
WS- 001032	9/11/17	9/11/18	Ground Floor	Bottle Filler	In hallway adjacent to restrooms	WF-92017-001032	2/21/18	FT-FY18--92017-001032-A	<1	FT-FY18--92017-001032-B	<1

Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation											
RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 001028	9/11/17	9/11/18	Ground Floor	Food Prep Sink	In kitchen adjacent to room 110	WF-92017-001028	2/21/18	FT-FY18--92017-001028-A	<1	FT-FY18--92017-001028-B	<1