

Benning Stoddert RC Lead in Water Test Results

FY22 Filter Test

-	11=111111111111111111111111111111111111												
		Less than 5ppb - Devices requiring no remediation											
	Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
	WS- 001028	1/4/2022	1/4/2023	Ground Floor	Food Prep Sink	In kitchen adjacent to room 110	WF-01042022-001028	3/4/2022	FT-FY22-02212022-001028-A	<1	FT-FY22-02212022-001028-B	<1	