



Benning Stoddert Recreation Center Lead in Water Test Results

FY23 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 001028	12/21/2022	12/21/2023	Ground Floor	Food Prep Sink	In kitchen adjacent to room 110	WF-12212022-001028	2/21/2023	FT-FY23-02022023-001028-A	<1	FT-FY23-02022023-001028-B	<1
WS- 001031	3/28/2022	3/28/2023	Ground Floor	Cooler	In hallway adjacent to restrooms Low Right	WF-03282022-001031	2/21/2023	FT-FY23-02022023-001031-A	<1	FT-FY23-02022023-001031-B	<1
WS- 001032	3/28/2022	3/28/2023	Ground Floor	Bottle Filler	In hallway adjacent to restrooms	WF-03282022-001032	2/21/2023	FT-FY23-02022023-001032-A	<1	FT-FY23-02022023-001032-B	<1