



# Brent ES Lead Water Test Results



## FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation											
RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009310	6/30/2017	6/30/2018	1	Cooler	In classroom 116	WF-62017-009310	11/8/2017	FT-FY18-62017-009310-A	<1	FT-FY18-62017-009310-B	<1
WS- 009314	6/30/2017	6/30/2018	1	Cooler	In classroom 110	WF-62017-009314	11/8/2017	FT-FY18-62017-009314-A	<1	FT-FY18-62017-009314-B	<1
WS- 009315	10/23/2017	10/23/2018	1	Classroom Faucet	In classroom 110	WF-102017-009315	11/8/2017	FT-FY18-102017-009315-A	<1	FT-FY18-102017-009315-B	<1
WS- 009318	6/30/2017	6/30/2018	1	Cooler	In classroom 104	WF-62017-009318	11/8/2017	FT-FY18-62017-009318-A	<1	FT-FY18-62017-009318-B	<1
WS- 009326	6/30/2017	6/30/2018	2	Cooler	In hallway across from room 210	WF-62017-009326	11/8/2017	FT-FY18-62017-009326-A	<1	FT-FY18-62017-009326-B	<1
WS- 009327	6/30/2017	6/30/2018	2	Break Room	In staff lounge 211	WF-62017-009327	11/8/2017	FT-FY18-62017-009327-A	<1	FT-FY18-62017-009327-B	<1
WS- 009331	6/30/2017	6/30/2018	2	Cooler	In hallway across from room 204	WF-62017-009331	11/8/2017	FT-FY18-62017-009331-A	<1	FT-FY18-62017-009331-B	<1
WS- 009336	6/30/2017	6/30/2018	3	Cooler	In hallway across from room 304	WF-62017-009336	11/8/2017	FT-FY18-62017-009336-A	<1	FT-FY18-62017-009336-B	<1

## Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation									
RECORD ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 009324	1	Food Prep Sink	In kitchen room 120D Right	11/8/2017	FT-FY18-102017-009324-A	<1	FT-FY18-102017-009324-B	<1	