



BROOKLAND LEAD WATER TEST RESULTS

May 24th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	BROOKLAND MS	5/13/2016	WS- 010454	Classroom	2	In classroom 2410	WT-042916-10471- A	1.32	WT-042916-10471- B	< 1			
2	BROOKLAND MS	5/13/2016	WS- 010453	Break Room	2	In staff lounge 2213	WT-042916-10470- A	1.01	WT-042916-10470- B	< 1			
3	BROOKLAND MS	5/13/2016	WS- 010452	Classroom	2	In classroom 2210 art room	WT-042916-10469- A	< 1	WT-042916-10469- B	< 1			
4	BROOKLAND MS	5/13/2016	WS- 010451	Classroom	2	In classroom 2210 art room	WT-042916-10468- A	< 1	WT-042916-10468- B	< 1			
5	BROOKLAND MS	5/13/2016	WS- 010450	Classroom	2	In classroom 2210 art room	WT-042916-10467- A	< 1	WT-042916-10467- B	< 1			
6	BROOKLAND MS	5/13/2016	WS- 010449	Classroom	Basement	In classroom L305	WT-042916-10466- A	< 1	WT-042916-10466- B	< 1			
7	BROOKLAND MS	5/13/2016	WS- 010448	Classroom	2	In science room 2307 north wall	WT-042916-10465- A	3.76	WT-042916-10465- B	< 1			
8	BROOKLAND MS	5/13/2016	WS- 010447	Classroom	2	In science room 2307 south wall	WT-042916-10464- A	1.23	WT-042916-10464- B	< 1			
9	BROOKLAND MS	5/13/2016	WS- 010446	Classroom	2	In science room 2307 south wall	WT-042916-10463- A	2.51	WT-042916-10463- B	< 1			
10	BROOKLAND MS	5/13/2016	WS- 010445	Classroom	2	In science room 2307 south wall	WT-042916-10462- A	1.59	WT-042916-10462- B	< 1			
11	BROOKLAND MS	5/13/2016	WS- 010444	Classroom	2	In science room 2307 east wall last from left	WT-042916-10461- A	< 1	WT-042916-10461- B	< 1			
12	BROOKLAND MS	5/13/2016	WS- 010443	Classroom	2	In science room 2307 east wall third from left	WT-042916-10460- A	1.23	WT-042916-10460- B	< 1			
13	BROOKLAND MS	5/13/2016	WS- 010442	Classroom	2	In science room 2307 east wall second from left	WT-042916-10459- A	1.68	WT-042916-10459- B	< 1			
14	BROOKLAND MS	5/13/2016	WS- 010441	Classroom	2	In science room 2307 east wall first from left	WT-042916-10458- A	1.02	WT-042916-10458- B	< 1			
15	BROOKLAND MS	5/13/2016	WS- 010440	Classroom	2	In science room 2307 west wall	WT-042916-10457- A	6.14	WT-042916-10457- B	< 1			
16	BROOKLAND MS	5/13/2016	WS- 010439	Classroom	2	In science room 2307 west wall	WT-042916-10456- A	5.97	WT-042916-10456- B	< 1			
17	BROOKLAND MS	5/13/2016	WS- 010438	Break Room	2	In teachers work room 2417	WT-042916-10455- A	< 1	WT-042916-10455- B	< 1			
18	BROOKLAND MS	5/13/2016	WS- 010437	Cooler	2	In hallway across from 2305 C wing	WT-042916-10454- A	< 1	WT-042916-10454- B	< 1			
19	BROOKLAND MS	5/13/2016	WS- 010436	Cooler	2	In hallway across from 2305 C wing	WT-042916-10453- A	< 1	WT-042916-10453- B	< 1			
20	BROOKLAND MS	5/13/2016	WS- 010435	Cooler	2	In hallway across from 2305 C wing (bottle filler)	WT-042916-10452- A	< 1	WT-042916-10452- B	< 1			
21	BROOKLAND MS	5/13/2016	WS- 010434	Classroom	2	In work room 2104	WT-042916-10451- A	< 1	WT-042916-10451- B	< 1			
22	BROOKLAND MS	5/13/2016	WS- 010433	Classroom	2	In class room would languages	WT-042916-10450- A	< 1	WT-042916-10450- B	< 1			
23	BROOKLAND MS	5/13/2016	WS- 010432	Cooler	2	In hallway adjacent to world languages	WT-042916-10449- A	< 1	WT-042916-10449- B	< 1			
24	BROOKLAND MS	5/13/2016	WS- 010431	Cooler	2	In hallway adjacent to world languages	WT-042916-10448- A	< 1	WT-042916-10448- B	< 1			
25	BROOKLAND MS	5/13/2016	WS- 010430	Cooler	2	In hallway adjacent to world languages (bottle filler)	WT-042916-10447- A	< 1	WT-042916-10447- B	< 1			
26	BROOKLAND MS	5/13/2016	WS- 010429	Classroom	1	In performing arts room 1130	WT-042916-10446- A	12.1	WT-042916-10446- B	< 1			
27	BROOKLAND MS	5/13/2016	WS- 010428	Classroom	1	In music room 1133	WT-042916-10445- A	< 1	WT-042916-10445- B	< 1			
28	BROOKLAND MS	5/13/2016	WS- 010427	Classroom	1	In science storage room 1305	WT-042916-10444- A	4.44	WT-042916-10444- B	< 1			
29	BROOKLAND MS	5/13/2016	WS- 010426	Classroom	Basement	In science room L304 north wall	WT-042916-10443- A	1.77	WT-042916-10443- B	< 1			
30	BROOKLAND MS	5/13/2016	WS- 010425	Classroom	Basement	In science room L304 west wall	WT-042916-10442- A	2.34	WT-042916-10442- B	< 1			
31	BROOKLAND MS	5/13/2016	WS- 010424	Classroom	Basement	In science room L304 west wall	WT-042916-10441- A	< 1	WT-042916-10441- B	< 1			
32	BROOKLAND MS	5/13/2016	WS- 010423	Classroom	Basement	In science room L304 south wall	WT-042916-10440- A	2.5	WT-042916-10440- B	< 1			
33	BROOKLAND MS	5/13/2016	WS- 010422	Classroom	Basement	In science room L304 south wall	WT-042916-10439- A	< 1	WT-042916-10439- B	< 1			
34	BROOKLAND MS	5/13/2016	WS- 010421	Classroom	Basement	In science room L304 east wall	WT-042916-10438- A	2.28	WT-042916-10438- B	< 1			
35	BROOKLAND MS	5/13/2016	WS- 010420	Classroom	Basement	In science room L304 east wall	WT-042916-10437- A	< 1	WT-042916-10437- B	6.82			
36	BROOKLAND MS	5/13/2016	WS- 010419	Classroom	Basement	In science room L304 east wall	WT-042916-10436- A	1.92	WT-042916-10436- B	< 1			
37	BROOKLAND MS	5/13/2016	WS- 010418	Break Room	Basement	In room L417	WT-042916-10435- A	< 1	WT-042916-10435- B	< 1			
38	BROOKLAND MS	5/13/2016	WS- 010417	Cooler	Basement	In hallway across from L303 C wing	WT-042916-10434- A	< 1	WT-042916-10434- B	< 1			
39	BROOKLAND MS	5/13/2016	WS- 010416	Cooler	Basement	In hallway across from L303 C wing	WT-042916-10433- A	< 1	WT-042916-10433- B	< 1			
40	BROOKLAND MS	5/13/2016	WS- 010415	Cooler	Basement	In hallway across from L303 C wing (bottle filler)	WT-042916-10432- A	< 1	WT-042916-10432- B	< 1			
41	BROOKLAND MS	5/13/2016	WS- 010414	Classroom	Basement	In classroom L410	WT-042916-10431- A	< 1	WT-042916-10431- B	< 1			
42	BROOKLAND MS	5/13/2016	WS- 010413	Cooler	Basement	In hallway adjacent to restrooms	WT-042916-10430- A	< 1	WT-042916-10430- B	< 1			
43	BROOKLAND MS	5/13/2016	WS- 010412	Cooler	Basement	In hallway adjacent to restrooms	WT-042916-10429- A	< 1	WT-042916-10429- B	< 1			
44	BROOKLAND MS	5/13/2016	WS- 010411	Cooler	Basement	In hallway adjacent to restrooms(bottle filler)	WT-042916-10428- A	< 1	WT-042916-10428- B	< 1			
45	BROOKLAND MS	5/13/2016	WS- 010410	Health Suite	Basement	In room L202	WT-042916-10427- A	< 1	WT-042916-10427- B	< 1			
46	BROOKLAND MS	5/13/2016	WS- 009388	Classroom	Basement	In classroom L201	WT-042916-9405- A	2.18	WT-042916-9405- B	< 1			
47	BROOKLAND MS	5/13/2016	WS- 009387	Utility	Basement	In water room L130	WT-042916-9404- A	18.8	WT-042916-9404- B	< 1	Filter will be installed and retested		
48	BROOKLAND MS	5/13/2016	WS- 009386	Cooler	Basement	In hallway across from L201	WT-042916-9403- A	< 1	WT-042916-9403- B	< 1			
49	BROOKLAND MS	5/13/2016	WS- 009385	Cooler	Basement	In hallway across from L201	WT-042916-9402- A	< 1	WT-042916-9402- B	< 1			
50	BROOKLAND MS	5/13/2016	WS- 009384	Cooler	Basement	In hallway across from L201	WT-042916-9401- A	< 1	WT-042916-9401- B	< 1			
51	BROOKLAND MS	5/13/2016	WS- 009383	Cooler	Basement	In hallway across from L201	WT-042916-9400- A	< 1	WT-042916-9400- B	< 1			



BROOKLAND LEAD WATER TEST RESULTS

May 24th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
52	BROOKLAND MS	5/13/2016	WS- 009382	Cooler	Basement	In hallway across from L201 (bottle filler) Right High	WT-042916-9399- A	< 1	WT-042916-9399- B	< 1			
53	BROOKLAND MS	5/13/2016	WS- 009381	Cooler	Basement	In hallway across from L201 (bottle filler) Left High	WT-042916-9398- A	< 1	WT-042916-9398- B	< 1			
54	BROOKLAND MS	5/13/2016	WS- 009380	Classroom	1	In classroom 1410	WT-042916-9397- A	< 1	WT-042916-9397- B	< 1			
55	BROOKLAND MS	5/13/2016	WS- 009379	Break Room	1	In teachers room 1417	WT-042916-9396- A	< 1	WT-042916-9396- B	< 1			
56	BROOKLAND MS	5/12/2016	WS- 009378	Classroom	1	In science room 1304 west wall Right	WT-042916-9395- A	4.75	WT-042916-9395- B	< 1			
57	BROOKLAND MS	5/13/2016	WS- 009377	Classroom	1	In science room 1304 west wall Left	WT-042916-9394- A	1.91	WT-042916-9394- B	< 1			
58	BROOKLAND MS	5/12/2016	WS- 009376	Classroom	1	In science room 1304 south wall Right	WT-042916-9393- A	1.03	WT-042916-9393- B	< 1			
59	BROOKLAND MS	5/13/2016	WS- 009375	Classroom	1	In science room 1304 south wall Left	WT-042916-9392- A	< 1	WT-042916-9392- B	< 1			
60	BROOKLAND MS	5/12/2016	WS- 009374	Classroom	1	In science room 1304 east wall Right	WT-042916-9391- A	< 1	WT-042916-9391- B	< 1			
61	BROOKLAND MS	5/13/2016	WS- 009373	Classroom	1	In science room 1304 east wall Mid	WT-042916-9390- A	4.68	WT-042916-9390- B	< 1			
62	BROOKLAND MS	5/12/2016	WS- 009372	Classroom	1	In science room 1304 east wall Left	WT-042916-9389- A	< 1	WT-042916-9389- B	< 1			
63	BROOKLAND MS	5/12/2016	WS- 009371	Classroom	1	In science room 1304 north wall	WT-042916-9388- A	4.47	WT-042916-9388- B	< 1			
64	BROOKLAND MS	5/12/2016	WS- 009370	Cooler	1	In hallway across from 1303 C wing Right Low	WT-042916-9387- A	< 1	WT-042916-9387- B	< 1			
65	BROOKLAND MS	5/12/2016	WS- 009369	Cooler	1	In hallway across from room 1303 Left High	WT-042916-9386- A	< 1	WT-042916-9386- B	< 1			
66	BROOKLAND MS	5/13/2016	WS- 009368	Other	1	In hallway C wing across 1303 "bottle filler" Left High	WT-042916-9385- A	< 1	WT-042916-9385- B	< 1			
67	BROOKLAND MS	5/12/2016	WS- 009367	Cooler	1	In hallway adjacent to cafeteria B wing Right Low	WT-042916-9384- A	< 1	WT-042916-9384- B	< 1			
68	BROOKLAND MS	5/12/2016	WS- 009366	Cooler	1	In hallway adjacent to cafeteria B wing Left High	WT-042916-9383- A	< 1	WT-042916-9383- B	< 1			
69	BROOKLAND MS	5/13/2016	WS- 009365	Cooler	1	In hallway adjacent to cafeteria B wing Left High	WT-042916-9382- A	< 1	WT-042916-9382- B	< 1			
70	BROOKLAND MS	5/13/2016	WS- 009364	Kitchen	1	In kitchen sink across from dishwashing sink Right	WT-042916-9381- A	< 1	WT-042916-9381- B	< 1			
71	BROOKLAND MS	5/13/2016	WS- 009363	Kitchen	1	In kitchen sink across from dishwashing sink Left	WT-042916-9380- A	< 1	WT-042916-9380- B	< 1			
72	BROOKLAND MS	5/12/2016	WS- 009362	Kitchen	1	In kitchen dishwasher sink nozzle sprayer	WT-042916-9379- A	< 1	WT-042916-9379- B	< 1			
73	BROOKLAND MS	5/12/2016	WS- 009361	Kitchen	1	In kitchen in front of ice maker(middle)	WT-042916-9378- A	< 1	WT-042916-9378- B	< 1			
74	BROOKLAND MS	5/13/2016	WS- 009360	Kitchen	1	In kitchen on wall adjacent to icemaker	WT-042916-9377- A	< 1	WT-042916-9377- B	< 1			
75	BROOKLAND MS	5/13/2016	WS- 009359	Kitchen	1	In kitchen icemaker	WT-042916-9376- A	< 1	WT-042916-9376- B	< 1			
76	BROOKLAND MS	5/13/2016	WS- 009358	Break Room	1	In main office kitchenette 1112	WT-042916-9375- A	< 1	WT-042916-9375- B	< 1			

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.