



Brookland MS Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009358	6/10/2019	6/10/2020	1	Break Room	In staff lounge in main office 1112	WF-06102019-009358	12/31/2019	FT-FY20-122019-009358-A	<1	FT-FY20-122019-009358-B	<1
WS- 009365	6/10/2019	6/10/2020	1	Bottle Filler	In hallway adjacent to girls' and boys' restrooms (bottle filler)	WF-06102019-009365	12/31/2019	FT-FY20-122019-009365-A	<1	FT-FY20-122019-009365-B	<1
WS- 009366	6/10/2019	6/10/2020	1	Cooler	In hallway adjacent to girls' and boys' restrooms High Left	WF-06102019-009366	12/31/2019	FT-FY20-122019-009366-A	<1	FT-FY20-122019-009366-B	<1
WS- 009367	6/10/2019	6/10/2020	1	Cooler	In hallway adjacent to girls' and boys' restrooms Low Right	WF-06102019-009367	12/31/2019	FT-FY20-122019-009367-A	<1	FT-FY20-122019-009367-B	<1
WS- 009369	6/10/2019	6/10/2020	1	Cooler	In hallway across from room 1303 High Left	WF-06102019-009369	12/31/2019	FT-FY20-122019-009369-A	<1	FT-FY20-122019-009369-B	<1
WS- 009370	6/10/2019	6/10/2020	1	Cooler	In hallway across from room 1303 Low Right	WF-06102019-009370	12/31/2019	FT-FY20-122019-009370-A	<1	FT-FY20-122019-009370-B	<1
WS- 009379	6/10/2019	6/10/2020	1	Break Room	In staff workroom 1417	WF-06102019-009379	12/31/2019	FT-FY20-122019-009379-A	<1	FT-FY20-122019-009379-B	<1
WS- 009381	6/10/2019	6/10/2020	Basement	Bottle Filler	In hallway across from room L201 (bottle filler)	WF-06102019-009381	12/31/2019	FT-FY20-122019-009381-A	<1	FT-FY20-122019-009381-B	<1
WS- 009382	6/10/2019	6/10/2020	Basement	Bottle Filler	In hallway across from room L201 (bottle filler)	WF-06102019-009382	12/31/2019	FT-FY20-122019-009382-A	<1	FT-FY20-122019-009382-B	<1
WS- 009383	6/10/2019	6/10/2020	Basement	Cooler	In hallway across from room L201 Low Right	WF-06102019-009383	12/31/2019	FT-FY20-122019-009383-A	<1	FT-FY20-122019-009383-B	<1
WS- 009384	6/10/2019	6/10/2020	Basement	Cooler	In hallway across from room L201 High Left	WF-06102019-009384	12/31/2019	FT-FY20-122019-009384-A	<1	FT-FY20-122019-009384-B	<1
WS- 009385	6/10/2019	6/10/2020	Basement	Cooler	In hallway across from room L201 Low Left	WF-06102019-009385	12/31/2019	FT-FY20-122019-009385-A	<1	FT-FY20-122019-009385-B	<1
WS- 009386	6/10/2019	6/10/2020	Basement	Cooler	In hallway across from room L201 High Left	WF-06102019-009386	12/31/2019	FT-FY20-122019-009386-A	<1	FT-FY20-122019-009386-B	<1
WS- 010410	6/10/2019	6/10/2020	Basement	Health Suite	In health suite L202	WF-06102019-010410	12/31/2019	FT-FY20-122019-010410-A	<1	FT-FY20-122019-010410-B	<1
WS- 010411	6/10/2019	6/10/2020	Basement	Bottle Filler	In hallway adjacent to girls' and boys' restrooms (bottle filler)	WF-06102019-010411	12/31/2019	FT-FY20-122019-010411-A	<1	FT-FY20-122019-010411-B	<1
WS- 010412	6/10/2019	6/10/2020	Basement	Cooler	In hallway adjacent to girls' and boys' restrooms High Left	WF-06102019-010412	12/31/2019	FT-FY20-122019-010412-A	<1	FT-FY20-122019-010412-B	<1
WS- 010413	6/10/2019	6/10/2020	Basement	Cooler	In hallway adjacent to girls' and boys' restrooms Low Right	WF-06102019-010413	12/31/2019	FT-FY20-122019-010413-A	<1	FT-FY20-122019-010413-B	<1
WS- 010415	6/10/2019	6/10/2020	Basement	Bottle Filler	In hallway across from room L303 C wing (bottle filler)	WF-06102019-010415	12/31/2019	FT-FY20-122019-010415-A	<1	FT-FY20-122019-010415-B	<1
WS- 010416	6/10/2019	6/10/2020	Basement	Cooler	In hallway across from room L303 C wing Low Right	WF-06102019-010416	12/31/2019	FT-FY20-122019-010416-A	<1	FT-FY20-122019-010416-B	<1
WS- 010417	6/10/2019	6/10/2020	Basement	Cooler	In hallway across from room L303 C wing High Left	WF-06102019-010417	12/31/2019	FT-FY20-122019-010417-A	<1	FT-FY20-122019-010417-B	<1
WS- 010418	6/10/2019	6/10/2020	Basement	Break Room	In staff workroom L417	WF-06102019-010418	12/31/2019	FT-FY20-122019-010418-A	<1	FT-FY20-122019-010418-B	<1
WS- 010430	6/10/2019	6/10/2020	2	Bottle Filler	In hallway adjacent to boys' restrooms (bottle filler)	WF-06102019-010430	12/31/2019	FT-FY20-122019-010430-A	<1	FT-FY20-122019-010430-B	<1
WS- 010431	6/10/2019	6/10/2020	2	Cooler	In hallway adjacent to boys' restroom High Left	WF-06102019-010431	12/31/2019	FT-FY20-122019-010431-A	<1	FT-FY20-122019-010431-B	<1
WS- 010432	6/10/2019	6/10/2020	2	Cooler	In hallway adjacent to boys' restroom Low Right	WF-06102019-010432	12/31/2019	FT-FY20-122019-010432-A	<1	FT-FY20-122019-010432-B	<1
WS- 010436	6/10/2019	6/10/2020	2	Cooler	In hallway across from room 2305 High Left	WF-06102019-010436	12/31/2019	FT-FY20-122019-010436-A	<1	FT-FY20-122019-010436-B	<1
WS- 010437	6/10/2019	6/10/2020	2	Cooler	In hallway across from room 2305 Low Right	WF-06102019-010437	12/31/2019	FT-FY20-122019-010437-A	<1	FT-FY20-122019-010437-B	<1
WS- 010438	6/10/2019	6/10/2020	2	Break Room	In staff workroom 2417	WF-06102019-010438	12/31/2019	FT-FY20-122019-010438-A	<1	FT-FY20-122019-010438-B	<1
WS- 010453	6/10/2019	6/10/2020	2	Break Room	In staff lounge 2213	WF-06102019-010453	12/31/2019	FT-FY20-122019-010453-A	<1	FT-FY20-122019-010453-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009360	7/12/2019	7/12/2020	1	Food Prep Sink	In kitchen on wall adjacent to icemaker	WF-07122019-009360	12/31/2019	FT-FY20-122019-009360-A	<1	FT-FY20-122019-009360-B	<1
WS- 009361	7/12/2019	7/12/2020	1	Food Prep Sink	In kitchen on island	WF-07122019-009361	12/31/2019	FT-FY20-122019-009361-A	<1	FT-FY20-122019-009361-B	<1