



Brookland Middle School Lead in Water Test Results

FY24 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-009358	7/10/2023	7/10/2024	1	Break Room	In staff lounge in main office 1112	WF-07102023-009358	12/8/2023	FT-FY24-11012023-009358-A	<1	FT-FY24-11012023-009358-B	<1
WS-009365	4/19/2023	4/19/2024	1	Bottle Filler	In hallway adjacent to girls' and boys' restrooms (bottle filler)	WF-04192023-009365	12/8/2023	FT-FY24-11012023-009365-A	<1	FT-FY24-11012023-009365-B	<1
WS-009366	4/19/2023	4/19/2024	1	Cooler	In hallway adjacent to girls' and boys' restrooms High Left	WF-04192023-009366	12/8/2023	FT-FY24-11012023-009366-A	1.0	FT-FY24-11012023-009366-B	<1
WS-009367	4/19/2023	4/19/2024	1	Cooler	In hallway adjacent to girls' and boys' restrooms Low Right	WF-04192023-009367	12/8/2023	FT-FY24-11012023-009367-A	<1	FT-FY24-11012023-009367-B	<1
WS-009369	7/10/2023	7/10/2024	1	Cooler	In hallway across from room 1303 High Left	WF-07102023-009369	12/8/2023	FT-FY24-11012023-009369-A	<1	FT-FY24-11012023-009369-B	<1
WS-009370	7/10/2023	7/10/2024	1	Cooler	In hallway across from room 1303 Low Right	WF-07102023-009370	12/8/2023	FT-FY24-11012023-009370-A	<1	FT-FY24-11012023-009370-B	<1
WS-009379	7/10/2023	7/10/2024	1	Break Room	In staff workroom 1417	WF-07102023-009379	12/8/2023	FT-FY24-11012023-009379-A	<1	FT-FY24-11012023-009379-B	<1
WS-009381	4/19/2023	4/19/2024	Basement	Bottle Filler	In hallway across from room L201 (bottle filler)	WF-04192023-009381	12/8/2023	FT-FY24-11012023-009381-A	<1	FT-FY24-11012023-009381-B	<1
WS-009385	4/19/2023	4/19/2024	Basement	Cooler	In hallway across from room L201 Low Left	WF-04192023-009385	12/8/2023	FT-FY24-11012023-009385-A	<1	FT-FY24-11012023-009385-B	<1
WS-009386	4/19/2023	4/19/2024	Basement	Cooler	In hallway across from room L201 High Left	WF-04192023-009386	12/8/2023	FT-FY24-11012023-009386-A	<1	FT-FY24-11012023-009386-B	<1
WS-010410	7/10/2023	7/10/2024	Basement	Health Suite	In health suite L202	WF-07102023-010410	12/8/2023	FT-FY24-11012023-010410-A	<1	FT-FY24-11012023-010410-B	<1
WS-010411	4/19/2023	4/19/2024	Basement	Bottle Filler	In hallway adjacent to girls' and boys' restrooms (bottle filler)	WF-04192023-010411	12/8/2023	FT-FY24-11012023-010411-A	<1	FT-FY24-11012023-010411-B	<1
WS-010412	4/19/2023	4/19/2024	Basement	Cooler	In hallway adjacent to girls' and boys' restrooms High Left	WF-04192023-010412	12/8/2023	FT-FY24-11012023-010412-A	<1	FT-FY24-11012023-010412-B	<1
WS-010413	4/19/2023	4/19/2024	Basement	Cooler	In hallway adjacent to girls' and boys' restrooms Low Right	WF-04192023-010413	12/8/2023	FT-FY24-11012023-010413-A	<1	FT-FY24-11012023-010413-B	<1
WS-010415	4/19/2023	4/19/2024	Basement	Bottle Filler	In hallway across from room L303 C wing (bottle filler)	WF-04192023-010415	12/8/2023	FT-FY24-11012023-010415-A	<1	FT-FY24-11012023-010415-B	<1
WS-010416	4/19/2023	4/19/2024	Basement	Cooler	In hallway across from room L303 C wing Low Right	WF-04192023-010416	12/8/2023	FT-FY24-11012023-010416-A	<1	FT-FY24-11012023-010416-B	<1
WS-010417	4/19/2023	4/19/2024	Basement	Cooler	In hallway across from room L303 C wing High Left	WF-04192023-010417	12/8/2023	FT-FY24-11012023-010417-A	<1	FT-FY24-11012023-010417-B	<1
WS-010418	7/10/2023	7/10/2024	Basement	Break Room	In staff workroom L417	WF-07102023-010418	12/8/2023	FT-FY24-11012023-010418-A	<1	FT-FY24-11012023-010418-B	<1
WS-010430	4/19/2023	4/19/2024	2	Bottle Filler	In hallway adjacent to boys' restrooms (bottle filler)	WF-04192023-010430	12/8/2023	FT-FY24-11012023-010430-A	<1	FT-FY24-11012023-010430-B	<1
WS-010431	4/19/2023	4/19/2024	2	Cooler	In hallway adjacent to boys' restroom High Left	WF-04192023-010431	12/8/2023	FT-FY24-11012023-010431-A	<1	FT-FY24-11012023-010431-B	<1
WS-010432	4/19/2023	4/19/2024	2	Cooler	In hallway adjacent to boys' restroom Low Right	WF-04192023-010432	12/8/2023	FT-FY24-11012023-010432-A	<1	FT-FY24-11012023-010432-B	<1
WS-010436	4/19/2023	4/19/2024	2	Cooler	In hallway across from room 2305 High Left	WF-04192023-010436	12/8/2023	FT-FY24-11012023-010436-A	<1	FT-FY24-11012023-010436-B	<1
WS-010438	7/10/2023	7/10/2024	2	Break Room	In staff workroom 2417	WF-07102023-010438	12/8/2023	FT-FY24-11012023-010438-A	<1	FT-FY24-11012023-010438-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-009360	1/9/2023	1/9/2024	1	Food Prep Sink	In kitchen on wall adjacent to icemaker	WF-01092023-009360	12/8/2023	FT-FY24-11012023-009360-A	<1	FT-FY24-11012023-009360-B	<1
WS-009361	1/9/2023	1/9/2024	1	Food Prep Sink	In kitchen on island	WF-01092023-009361	12/8/2023	FT-FY24-11012023-009361-A	<1	FT-FY24-11012023-009361-B	<1