



Brookland Middle School Lead in Water Test Results

FY25 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-009358	4/10/2024	4/10/2025	1	Break Room	In staff lounge in main office 1112	WF-04102024-009358	12/11/2024	FT-FY25-10312024-009358-A	<2	FT-FY25-10312024-009358-B	<2
WS-009367	4/10/2024	4/10/2025	1	Cooler	In hallway adjacent to girls' and boys' restrooms Low Right	WF-04102024-009367	12/11/2024	FT-FY25-10312024-009367-A	<2	FT-FY25-10312024-009367-B	<2
WS-009369	4/10/2024	4/10/2025	1	Cooler	In hallway across from room 1303 High Left	WF-04102024-009369	12/11/2024	FT-FY25-10312024-009369-A	<2	FT-FY25-10312024-009369-B	<2
WS-009370	4/10/2024	4/10/2025	1	Cooler	In hallway across from room 1303 Low Right	WF-04102024-009370	12/11/2024	FT-FY25-10312024-009370-A	<2	FT-FY25-10312024-009370-B	<2
WS-009379	4/10/2024	4/10/2025	1	Break Room	In staff workroom 1417	WF-04102024-009379	12/11/2024	FT-FY25-10312024-009379-A	<2	FT-FY25-10312024-009379-B	<2
WS-009381	4/10/2024	4/10/2025	Basement	Bottle Filler	In hallway across from room L201 (bottle filler)	WF-04102024-009381	12/11/2024	FT-FY25-10312024-009381-A	<2	FT-FY25-10312024-009381-B	<2
WS-009385	4/10/2024	4/10/2025	Basement	Cooler	In hallway across from room L201 Low Left	WF-04102024-009385	12/11/2024	FT-FY25-10312024-009385-A	<2	FT-FY25-10312024-009385-B	<2
WS-009386	4/10/2024	4/10/2025	Basement	Cooler	In hallway across from room L201 High Left	WF-04102024-009386	12/11/2024	FT-FY25-10312024-009386-A	<2	FT-FY25-10312024-009386-B	<2
WS-010410	4/10/2024	4/10/2025	Basement	Health Suite	In health suite L202	WF-04102024-010410	12/11/2024	FT-FY25-10312024-010410-A	<2	FT-FY25-10312024-010410-B	<2
WS-010411	4/10/2024	4/10/2025	Basement	Bottle Filler	In hallway adjacent to girls' and boys' restrooms (bottle filler)	WF-04102024-010411	12/11/2024	FT-FY25-10312024-010411-A	<2	FT-FY25-10312024-010411-B	<2
WS-010412	4/10/2024	4/10/2025	Basement	Cooler	In hallway adjacent to girls' and boys' restrooms High Left	WF-04102024-010412	12/11/2024	FT-FY25-10312024-010412-A	<2	FT-FY25-10312024-010412-B	<2
WS-010413	4/10/2024	4/10/2025	Basement	Cooler	In hallway adjacent to girls' and boys' restrooms Low Right	WF-04102024-010413	12/11/2024	FT-FY25-10312024-010413-A	<2	FT-FY25-10312024-010413-B	<2
WS-010415	4/10/2024	4/10/2025	Basement	Bottle Filler	In hallway across from room L303 C wing (bottle filler)	WF-04102024-010415	12/11/2024	FT-FY25-10312024-010415-A	<2	FT-FY25-10312024-010415-B	<2
WS-010416	4/10/2024	4/10/2025	Basement	Cooler	In hallway across from room L303 C wing Low Right	WF-04102024-010416	12/11/2024	FT-FY25-10312024-010416-A	<2	FT-FY25-10312024-010416-B	<2
WS-010417	4/10/2024	4/10/2025	Basement	Cooler	In hallway across from room L303 C wing High Left	WF-04102024-010417	12/11/2024	FT-FY25-10312024-010417-A	<2	FT-FY25-10312024-010417-B	<2
WS-010418	4/10/2024	4/10/2025	Basement	Break Room	In staff workroom L417	WF-04102024-010418	12/11/2024	FT-FY25-10312024-010418-A	<2	FT-FY25-10312024-010418-B	<2
WS-010430	4/10/2024	4/10/2025	2	Bottle Filler	In hallway adjacent to boys' restrooms (bottle filler)	WF-04102024-010430	12/11/2024	FT-FY25-10312024-010430-A	<2	FT-FY25-10312024-010430-B	<2
WS-010431	4/10/2024	4/10/2025	2	Cooler	In hallway adjacent to boys' restroom High Left	WF-04102024-010431	12/11/2024	FT-FY25-10312024-010431-A	<2	FT-FY25-10312024-010431-B	<2
WS-010432	4/10/2024	4/10/2025	2	Cooler	In hallway adjacent to boys' restroom Low Right	WF-04102024-010432	12/11/2024	FT-FY25-10312024-010432-A	<2	FT-FY25-10312024-010432-B	<2
WS-010437	4/10/2024	4/10/2025	2	Cooler	In hallway across from room 2305 Low Right	WF-04102024-010437	12/11/2024	FT-FY25-10312024-010437-A	<2	FT-FY25-10312024-010437-B	<2
WS-010438	4/10/2024	4/10/2025	2	Break Room	In staff workroom 2417	WF-04102024-010438	12/11/2024	FT-FY25-10312024-010438-A	<2	FT-FY25-10312024-010438-B	<2
WS-010453	4/10/2024	4/10/2025	2	Break Room	In staff lounge 2213	WF-04102024-010453	12/11/2024	FT-FY25-10312024-010453-A	<2	FT-FY25-10312024-010453-B	<2

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-009360	12/11/2023	12/11/2024	1	Food Prep Sink	In kitchen on wall adjacent to icemaker	WF-12112023-009360	12/11/2024	FT-FY25-10312024-009360-A	<2	FT-FY25-10312024-009360-B	<2
WS-009361	12/11/2023	12/11/2024	1	Food Prep Sink	In kitchen on island	WF-12112023-009361	12/11/2024	FT-FY25-10312024-009361-A	<2	FT-FY25-10312024-009361-B	<2

Due to changes in water sampling analysis equipment at the laboratory from previous years, the level of detection (LOD) for lead in drinking water is now <2ppb.