



Brookland MS Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 009358	6/18/2018	6/18/2019	1	Break Room	In staff lounge in main office 1112	WF-06182018-009358	12/11/2018	FT-FY19-122018-009358-A	<1	FT-FY19-122018-009358-B	<1	
WS- 009365	6/18/2018	6/18/2019	1	Bottle Filler	In hallway adjacent to girls' and boys' restrooms (bottle filler)	WF-06182018-009365	12/11/2018	FT-FY19-122018-009365-A	<1	FT-FY19-122018-009365-B	<1	
WS- 009366	6/18/2018	6/18/2019	1	Cooler	In hallway adjacent to girls' and boys' restrooms	High Left	WF-06182018-009366	12/11/2018	FT-FY19-122018-009366-A	<1	FT-FY19-122018-009366-B	<1
WS- 009367	6/18/2018	6/18/2019	1	Cooler	In hallway adjacent to girls' and boys' restrooms	Low Right	WF-06182018-009367	12/11/2018	FT-FY19-122018-009367-A	<1	FT-FY19-122018-009367-B	<1
WS- 009369	6/18/2018	6/18/2019	1	Cooler	In hallway across from room 1303	High Left	WF-06182018-009369	12/11/2018	FT-FY19-122018-009369-A	<1	FT-FY19-122018-009369-B	<1
WS- 009370	6/18/2018	6/18/2019	1	Cooler	In hallway across from room 1303	Low Right	WF-06182018-009370	12/11/2018	FT-FY19-122018-009370-A	<1	FT-FY19-122018-009370-B	<1
WS- 009379	6/18/2018	6/18/2019	1	Break Room	In staff workroom 1417	WF-06182018-009379	12/11/2018	FT-FY19-122018-009379-A	<1	FT-FY19-122018-009379-B	<1	
WS- 009381	6/18/2018	6/18/2019	Basement	Bottle Filler	In hallway across from room L201 (bottle filler)	WF-06182018-009381	12/11/2018	FT-FY19-122018-009381-A	<1	FT-FY19-122018-009381-B	<1	
WS- 009382	6/18/2018	6/18/2019	Basement	Bottle Filler	In hallway across from room L201 (bottle filler)	WF-06182018-009382	12/11/2018	FT-FY19-122018-009382-A	<1	FT-FY19-122018-009382-B	<1	
WS- 009383	6/18/2018	6/18/2019	Basement	Cooler	In hallway across from room L201	High Right	WF-06182018-009383	12/11/2018	FT-FY19-122018-009383-A	<1	FT-FY19-122018-009383-B	<1
WS- 009384	6/18/2018	6/18/2019	Basement	Cooler	In hallway across from room L201	Low Right	WF-06182018-009384	12/11/2018	FT-FY19-122018-009384-A	<1	FT-FY19-122018-009384-B	<1
WS- 009385	6/18/2018	6/18/2019	Basement	Cooler	In hallway across from room L201	Low Left	WF-06182018-009385	12/11/2018	FT-FY19-122018-009385-A	<1	FT-FY19-122018-009385-B	<1
WS- 009386	6/18/2018	6/18/2019	Basement	Cooler	In hallway across from room L201	High Left	WF-06182018-009386	12/11/2018	FT-FY19-122018-009386-A	<1	FT-FY19-122018-009386-B	<1
WS- 010410	6/18/2018	6/18/2019	Basement	Health Suite	In health suite L202	WF-06182018-010410	12/11/2018	FT-FY19-122018-010410-A	<1	FT-FY19-122018-010410-B	<1	
WS- 010411	6/18/2018	6/18/2019	Basement	Bottle Filler	In hallway adjacent to girls' and boys' restrooms (bottle filler)	WF-06182018-010411	12/11/2018	FT-FY19-122018-010411-A	<1	FT-FY19-122018-010411-B	<1	
WS- 010412	6/18/2018	6/18/2019	Basement	Cooler	In hallway adjacent to girls' and boys' restrooms	High Left	WF-06182018-010412	12/11/2018	FT-FY19-122018-010412-A	<1	FT-FY19-122018-010412-B	<1
WS- 010413	6/18/2018	6/18/2019	Basement	Cooler	In hallway adjacent to girls' and boys' restrooms	Low Right	WF-06182018-010413	12/11/2018	FT-FY19-122018-010413-A	<1	FT-FY19-122018-010413-B	<1
WS- 010416	6/18/2018	6/18/2019	Basement	Cooler	In hallway across from room L303 C wing	High Left	WF-06182018-010416	12/11/2018	FT-FY19-122018-010416-A	<1	FT-FY19-122018-010416-B	<1
WS- 010417	6/18/2018	6/18/2019	Basement	Cooler	In hallway across from room L303 C wing	Low Right	WF-06182018-010417	12/11/2018	FT-FY19-122018-010417-A	<1	FT-FY19-122018-010417-B	<1
WS- 010418	6/18/2018	6/18/2019	Basement	Break Room	In staff workroom L417	WF-06182018-010418	12/11/2018	FT-FY19-122018-010418-A	<1	FT-FY19-122018-010418-B	<1	
WS- 010430	6/18/2018	6/18/2019	2	Bottle Filler	In hallway adjacent to boys' restrooms (bottle filler)	WF-06182018-010430	12/11/2018	FT-FY19-122018-010430-A	<1	FT-FY19-122018-010430-B	<1	
WS- 010431	6/18/2018	6/18/2019	2	Cooler	In hallway adjacent to boys' restroom	High Left	WF-06182018-010431	12/11/2018	FT-FY19-122018-010431-A	<1	FT-FY19-122018-010431-B	<1
WS- 010432	6/18/2018	6/18/2019	2	Cooler	In hallway adjacent to boys' restroom	Low Right	WF-06182018-010432	12/11/2018	FT-FY19-122018-010432-A	<1	FT-FY19-122018-010432-B	<1
WS- 010436	6/18/2018	6/18/2019	2	Cooler	In hallway across from room 2305	High Left	WF-06182018-010436	12/11/2018	FT-FY19-122018-010436-A	<1	FT-FY19-122018-010436-B	<1
WS- 010437	6/18/2018	6/18/2019	2	Cooler	In hallway across from room 2305	Low Right	WF-06182018-010437	12/11/2018	FT-FY19-122018-010437-A	<1	FT-FY19-122018-010437-B	<1
WS- 010438	6/18/2018	6/18/2019	2	Break Room	In staff workroom 2417	WF-06182018-010438	12/11/2018	FT-FY19-122018-010438-A	<1	FT-FY19-122018-010438-B	<1	
WS- 010453	6/18/2018	6/18/2019	2	Break Room	In staff lounge 2213	WF-06182018-010453	12/11/2018	FT-FY19-122018-010453-A	<1	FT-FY19-122018-010453-B	<1	

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009360	1	Food Prep Sink	In kitchen on wall adjacent to icemaker	12/11/2018	FT-FY19-122018-009360-A	<1	FT-FY19-122018-009360-B	<1
WS- 009361	1	Food Prep Sink	In kitchen on island	12/11/2018	FT-FY19-122018-009361-A	<1	FT-FY19-122018-009361-B	<1