



# BROWNE LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 BROWNE EC	4/30/2016	WS- 000846	Classroom	3	In room 3, fifth sink couter clockwise from east door Right	WT-042916-863- A	56.6	WT-042916-863- B	141	Filter will be installed and then retested			
2 BROWNE EC	4/30/2016	WS- 000837	Classroom	3	In room 1, fourth sink counter clockwise from east door	WT-042916-854- A	24.2	WT-042916-854- B	11.4	Filter will be installed and then retested			
3 BROWNE EC	5/1/2016	WS- 000836	Classroom	3	In room 1, third sink counterclockwise from east door Left	WT-042916-853- A	8	WT-042916-853- B	6.7				
4 BROWNE EC	4/30/2016	WS- 000835	Classroom	3	In room 1, second sink counter clockwise from east door Mid	WT-042916-852- A	22.8	WT-042916-852- B	23	Filter will be installed and then retested			
5 BROWNE EC	4/30/2016	WS- 000834	Classroom	3	In room 1, first sink counter clockwise from east door Right	WT-042916-851- A	5.5	WT-042916-851- B	3.6				
6 BROWNE EC	4/30/2016	WS- 000833	Classroom	3	In room 1, fifth sink counter clockwise from east door	WT-042916-850- A	21.6	WT-042916-850- B	2.9	Filter will be installed and then retested			
7 BROWNE EC	4/30/2016	WS- 000832	Classroom	3	In room 2, fifth sink counterclockwise from east door Right	WT-042916-849- A	26.4	WT-042916-849- B	10.5	Filter will be installed and then retested			
8 BROWNE EC	4/30/2016	WS- 000831	Classroom	3	In room 2, third sink counter clockwise from east door	WT-042916-848- A	264	WT-042916-848- B	6.2	Filter will be installed and then retested			
9 BROWNE EC	4/30/2016	WS- 000830	Classroom	3	South wall class room 2	WT-042916-847- A	< 1	WT-042916-847- B	< 1				
10 BROWNE EC	4/30/2016	WS- 000829	Classroom	3	In room 2, first sink counter clockwise from east door Mid	WT-042916-846- A	86.4	WT-042916-846- B	2.6	Filter will be installed and then retested			
11 BROWNE EC	4/30/2016	WS- 000828	Classroom	3	In room 2, fourth sink counter clockwise from east door	WT-042916-845- A	290	WT-042916-845- B	7.7	Filter will be installed and then retested			
12 BROWNE EC	4/30/2016	WS- 000827	Classroom	3	In room 3, fourth sink counterclockwise from east door	WT-042916-844- A	9.1	WT-042916-844- B	10.6				
13 BROWNE EC	4/30/2016	WS- 000826	Classroom	3	In room 3, first sink counter clockwise from east door Left	WT-042916-843- A	59.4	WT-042916-843- B	15	Filter will be installed and then retested			
14 BROWNE EC	4/30/2016	WS- 000825	Cooler	3	In room 3, second sink counter clockwise from east door Right	WT-042916-842- A	8.1	WT-042916-842- B	5.8				
15 BROWNE EC	4/30/2016	WS- 000824	Fountain	3	In hallway adjacent to northeast stairwell	WT-042916-841- A	< 1	WT-042916-841- B	< 1				
16 BROWNE EC	4/30/2016	WS- 000823	Cooler	3	In hallway adjacent to room 3	WT-042916-840- A	< 1	WT-042916-840- B	< 1				
17 BROWNE EC	4/30/2016	WS- 000822	Classroom	3	In room 3, third sink counter clockwise from east door	WT-042916-839- A	5.1	WT-042916-839- B	3.6				
18 BROWNE EC	4/30/2016	WS- 000821	Cooler	3	In hallway adjacent to room 328	WT-042916-838- A	< 1	WT-042916-838- B	< 1				
19 BROWNE EC	5/1/2016	WS- 000820	Fountain	1	In room 119	WT-042916-837- A	< 1	WT-042916-837- B	< 1				
20 BROWNE EC	5/1/2016	WS- 000819	Classroom	1	In room 119	WT-042916-836- A	< 1	WT-042916-836- B	< 1				
21 BROWNE EC	4/30/2016	WS- 000792	Kitchen	Basement	In kitchen across from unisex restroom Left	WT-042916-809- A	< 1	WT-042916-809- B	< 1				
22 BROWNE EC	4/30/2016	WS- 000789	Cooler	3	In hallway djacent to classroom 1	WT-042916-806- A	< 1	WT-042916-806- B	< 1				
23 BROWNE EC	4/30/2016	WS- 000788	Cooler	Basement	In girls locker room	WT-042916-805- A	< 1	WT-042916-805- B	< 1				
24 BROWNE EC	4/30/2016	WS- 000784	Fountain	1	In room 128 Left	WT-042916-801- A	< 1	WT-042916-801- B	< 1				
25 BROWNE EC	4/30/2016	WS- 000780	Classroom	1	In room 128 Right	WT-042916-797- A	2	WT-042916-797- B	< 1				
26 BROWNE EC	4/30/2016	WS- 000778	Cooler	2	In hallway, adjacent to room 2-217	WT-042916-795- A	< 1	WT-042916-795- B	< 1				
27 BROWNE EC	4/30/2016	WS- 000777	Cooler	1	In hallway djacent to room 213	WT-042916-794- A	< 1	WT-042916-794- B	< 1				



# BROWNE LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
28	BROWNE EC	4/30/2016	WS-000776	Fountain	2	In hallways adjacent to room number 235	WT-042916-793- A	< 1	WT-042916-793- B	< 1			
29	BROWNE EC	5/1/2016	WS-000775	Fountain	2	In hallway adjacent to stairwell 6	WT-042916-792- A	< 1	WT-042916-792- B	< 1			
30	BROWNE EC	5/1/2016	WS-000774	Cooler	2	In hallway adjacent to room 301	WT-042916-791- A	< 1	WT-042916-791- B	< 1			
31	BROWNE EC	4/30/2016	WS-000773	Cooler	2	In hallway adjacent to classroom 2-273	WT-042916-790- A	< 1	WT-042916-790- B	< 1			
32	BROWNE EC	4/30/2016	WS-000772	Classroom	2	In classroom 2-272	WT-042916-789- A	66.2	WT-042916-789- B	4.7	Filter will be installed and then retested		
33	BROWNE EC	4/30/2016	WS-000771	Cooler	2	In hallway adjacent to classroom 2-269	WT-042916-788- A	< 1	WT-042916-788- B	< 1			
34	BROWNE EC	4/30/2016	WS-000770	Fountain	1	In hallway adjacent to room 208	WT-042916-787- A	< 1	WT-042916-787- B	< 1			
35	BROWNE EC	4/30/2016	WS-000769	Classroom	1	In room 194 third sink counter clockwise from west door	WT-042916-786- A	27.3	WT-042916-786- B	< 1	Filter will be installed and then retested		
36	BROWNE EC	4/30/2016	WS-000768	Classroom	1	In room 194, fourth sink counterclockwise from west door	WT-042916-785- A	56.2	WT-042916-785- B	< 1	Filter will be installed and then retested		
37	BROWNE EC	4/30/2016	WS-000767	Classroom	1	In room 194, second sink counter clockwise from west door	WT-042916-784- A	8.3	WT-042916-784- B	< 1			
38	BROWNE EC	4/30/2016	WS-000766	Classroom	1	In room 194, first counter clockwise from west door	WT-042916-783- A	1.2	WT-042916-783- B	< 1			
39	BROWNE EC	4/30/2016	WS-000764	Classroom	1	In room 193	WT-042916-781- A	1.8	WT-042916-781- B	< 1			
40	BROWNE EC	4/30/2016	WS-000763	Fountain	1	In hallway adjacent to custodian closet on west hallway.	WT-042916-780- A	< 1	WT-042916-780- B	< 1			
41	BROWNE EC	4/30/2016	WS-000762	Cooler	1	In hallway adjacent to room 1-179	WT-042916-779- A	< 1	WT-042916-779- B	< 1			
42	BROWNE EC	4/30/2016	WS-000761	Cooler	1	In hallway adjacent to room 1-157	WT-042916-778- A	< 1	WT-042916-778- B	< 1			
43	BROWNE EC	5/1/2016	WS-000760	Fountain	1	In room 103	WT-042916-777- A	< 1	WT-042916-777- B	1.8			
44	BROWNE EC	5/1/2016	WS-000759	Classroom	1	In room 103	WT-042916-776- A	1	WT-042916-776- B	6.7			
45	BROWNE EC	4/30/2016	WS-000758	Health Suite	1	In health suite 1-154	WT-042916-775- A	< 1	WT-042916-775- B	< 1			
46	BROWNE EC	4/30/2016	WS-000757	Classroom	1	In classroom 1-137	WT-042916-774- A	7.8	WT-042916-774- B	< 1			
47	BROWNE EC	4/30/2016	WS-000756	Fountain	1	In classroom 1-137	WT-042916-773- A	1	WT-042916-773- B	< 1			
48	BROWNE EC	4/30/2016	WS-000755	Fountain	1	In classroom 1-140	WT-042916-772- A	< 1	WT-042916-772- B	< 1			
49	BROWNE EC	4/30/2016	WS-000754	Classroom	1	In classroom 1-140	WT-042916-771- A	< 1	WT-042916-771- B	< 1			
50	BROWNE EC	5/1/2016	WS-000753	Classroom	1	In room 108	WT-042916-770- A	< 1	WT-042916-770- B	< 1			
51	BROWNE EC	5/1/2016	WS-000752	Fountain	1	In room 108	WT-042916-769- A	< 1	WT-042916-769- B	< 1			
52	BROWNE EC	5/1/2016	WS-000751	Cooler	1	In hallway adjacent to room 108	WT-042916-768- A	< 1	WT-042916-768- B	< 1			
53	BROWNE EC	5/1/2016	WS-000750	Classroom	1	In room 111	WT-042916-767- A	< 1	WT-042916-767- B	< 1			
54	BROWNE EC	5/1/2016	WS-000749	Fountain	1	In room 111	WT-042916-766- A	< 1	WT-042916-766- B	< 1			
55	BROWNE EC	5/1/2016	WS-000748	Fountain	1	In room 099	WT-042916-765- A	11.2	WT-042916-765- B	< 1			
56	BROWNE EC	5/1/2016	WS-000747	Classroom	1	In room 099	WT-042916-764- A	< 1	WT-042916-764- B	< 1			
57	BROWNE EC	5/1/2016	WS-000746	Classroom	1	In social worker room 112 Left	WT-042916-763- A	< 1	WT-042916-763- B	< 1			
58	BROWNE EC	5/1/2016	WS-000745	Fountain	1	Social worker room 112	WT-042916-762- A	< 1	WT-042916-762- B	< 1			
59	BROWNE EC	5/1/2016	WS-000744	Cooler	1	In hallway adjacent to Room 119	WT-042916-761- A	< 1	WT-042916-761- B	< 1			
60	BROWNE EC	4/30/2016	WS-000743	Cooler	Basement	In boys locker room	WT-042916-760- A	< 1	WT-042916-760- B	< 1			
61	BROWNE EC	4/30/2016	WS-000742	Cooler	Basement	In hallway across from gymnasium, in between girls and boys bathrooms	WT-042916-759- A	< 1	WT-042916-759- B	< 1			
62	BROWNE EC	4/30/2016	WS-000741	Cooler	Basement	Gymnasium hallway adjacent to exit doors	WT-042916-758- A	< 1	WT-042916-758- B	< 1			
63	BROWNE EC	4/30/2016	WS-000740	Cooler	1	Adjacent to gymnasium	WT-042916-757- A	< 1	WT-042916-757- B	< 1			
64	BROWNE EC	4/30/2016	WS-000739	Classroom	1	In room 1-124	WT-042916-756- A	< 1	WT-042916-756- B	< 1			
65	BROWNE EC	4/30/2016	WS-000738	Fountain	1	In room 1-124 Left	WT-042916-755- A	< 1	WT-042916-755- B	< 1			
66	BROWNE EC	4/30/2016	WS-000737	Cooler	1	In hallway adjacent to room 1-124	WT-042916-754- A	< 1	WT-042916-754- B	< 1			
67	BROWNE EC	4/30/2016	WS-000736	Cooler	Basement	In cafeteria, other side of kitchen	WT-042916-753- A	< 1	WT-042916-753- B	< 1			
68	BROWNE EC	4/30/2016	WS-000735	Cooler	Basement	In cafeteria, near kitchen	WT-042916-752- A	< 1	WT-042916-752- B	< 1			
69	BROWNE EC	4/30/2016	WS-000734	Kitchen	Basement	In kitchen east wall hot water sink	WT-042916-751- A	< 1	WT-042916-751- B	< 1			
70	BROWNE EC	4/30/2016	WS-000733	Kitchen	Basement	In kitchen across from unisex restroom, other side of wall	WT-042916-750- A	< 1	WT-042916-750- B	< 1			
71	BROWNE EC	4/30/2016	WS-000732	Kitchen	Basement	In kitchen across from unisex bathroom Right	WT-042916-749- A	< 1	WT-042916-749- B	< 1			
72	BROWNE EC	4/30/2016	WS-000730	Kitchen	Basement	In kitchen adjacent to unisex bathroom	WT-042916-747- A	3.8	WT-042916-747- B	< 1			



# BROWNE LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
73 BROWNE EC	4/30/2016	WS- 000729	Utility	Basement	Main water source point in boiler room	WT-042916-746- A	2.2	WT-042916-746- B	1.1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.