



BUNKER HILL LEAD WATER TEST RESULTS

May 11th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest Results
1	BUNKER HILL ES	5/4/2016	WS- 002949	Utility	Basement	In a boiler room	WT-042916-2966- A	128	WT-042916-2966- B	34.4	Non-drinking Water Source Flush		
2	BUNKER HILL ES	5/4/2016	WS- 002950	Cooler	Basement	In the kitchen	WT-042916-2967- A	< 1	WT-042916-2967- B	< 1			
3	BUNKER HILL ES	5/4/2016	WS- 002951	Kitchen	Basement	Sink	WT-042916-2968- A	< 1	WT-042916-2968- B	< 1			
4	BUNKER HILL ES	5/4/2016	WS- 002952	Classroom	1	In room 103 Right	WT-042916-2969- A	< 1	WT-042916-2969- B	< 1			
5	BUNKER HILL ES	5/4/2016	WS- 002953	Fountain	1	In room 103 Left	WT-042916-2970- A	< 1	WT-042916-2970- B	< 1			
6	BUNKER HILL ES	5/4/2016	WS- 002954	Cooler	1	In hallway adjacent to room 144	WT-042916-2971- A	< 1	WT-042916-2971- B	< 1			
7	BUNKER HILL ES	5/4/2016	WS- 002955	Classroom	1	In room 105 Right	WT-042916-2972- A	< 1	WT-042916-2972- B	< 1			
8	BUNKER HILL ES	5/4/2016	WS- 002956	Fountain	1	In room 105 Left	WT-042916-2973- A	< 1	WT-042916-2973- B	< 1			
9	BUNKER HILL ES	5/4/2016	WS- 002957	Fountain	1	In room 105 Left	WT-042916-2974- A	< 1	WT-042916-2974- B	< 1			
10	BUNKER HILL ES	5/4/2016	WS- 002958	Classroom	1	In room 106 Right	WT-042916-2975- A	< 1	WT-042916-2975- B	< 1			
11	BUNKER HILL ES	5/4/2016	WS- 002959	Cooler	1	In lobby	WT-042916-2976- A	< 1	WT-042916-2976- B	< 1			
12	BUNKER HILL ES	5/4/2016	WS- 002960	Cooler	1	In healthsuit	WT-042916-2977- A	< 1	WT-042916-2977- B	< 1			
13	BUNKER HILL ES	5/4/2016	WS- 002961	Fountain	1	In room 108 Left	WT-042916-2978- A	< 1	WT-042916-2978- B	< 1			
14	BUNKER HILL ES	5/4/2016	WS- 002962	Classroom	1	In room 108 Right	WT-042916-2979- A	< 1	WT-042916-2979- B	< 1			
15	BUNKER HILL ES	5/4/2016	WS- 002963	Fountain	1	In room 109 Left	WT-042916-2980- A	< 1	WT-042916-2980- B	< 1			
16	BUNKER HILL ES	5/4/2016	WS- 002964	Classroom	1	In room 109 Right	WT-042916-2981- A	5.8	WT-042916-2981- B	< 1			
17	BUNKER HILL ES	5/4/2016	WS- 002965	Fountain	1	In room 110 Left	WT-042916-2982- A	< 1	WT-042916-2982- B	< 1			
18	BUNKER HILL ES	5/4/2016	WS- 002966	Classroom	1	In room 110 Right	WT-042916-2983- A	< 1	WT-042916-2983- B	< 1			
19	BUNKER HILL ES	5/4/2016	WS- 002967	Cooler	1	In hallway adjacent to room 110	WT-042916-2984- A	< 1	WT-042916-2984- B	< 1			
20	BUNKER HILL ES	5/5/2016	WS- 002968	Fountain	1	In room 111 Left	WT-042916-2985- A	< 1	WT-042916-2985- B	< 1			



BUNKER HILL LEAD WATER TEST RESULTS

May 11th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest Results
21	BUNKER HILL ES	5/4/2016	WS- 002969	Classroom	1	In room 111 Right	WT-042916-2986- A	< 1	WT-042916-2986- B	< 1			
22	BUNKER HILL ES	5/4/2016	WS- 002970	Classroom	1	In room 112	WT-042916-2987- A	< 1	WT-042916-2987- B	< 1			
23	BUNKER HILL ES	5/4/2016	WS- 002971	Break Room	1	Next to room 112	WT-042916-2988- A	1.9	WT-042916-2988- B	< 1			
24	BUNKER HILL ES	5/4/2016	WS- 002972	Cooler	1	In hallway across room131	WT-042916-2989- A	< 1	WT-042916-2989- B	< 1			
25	BUNKER HILL ES	5/4/2016	WS- 002978	Cooler	2	In hallway adjacent to room 210	WT-042916-2995- A	< 1	WT-042916-2995- B	< 1			
26	BUNKER HILL ES	5/4/2016	WS- 002979	Cooler	2	In hallway across the office 223	WT-042916-2996- A	< 1	WT-042916-2996- B	< 1			
27	BUNKER HILL ES	5/4/2016	WS- 002980	Cooler	2	In hallway adjacent to room 216	WT-042916-2997- A	< 1	WT-042916-2997- B	< 1			
28	BUNKER HILL ES	5/4/2016	WS- 002981	Cooler	2	In hallway adjacent to room 203	WT-042916-2998- A	< 1	WT-042916-2998- B	< 1			
29	BUNKER HILL ES	5/4/2016	WS- 002982	Classroom	2	In room 203 sink Mid	WT-042916-2999- A	10.4	WT-042916-2999- B	9.5			
30	BUNKER HILL ES	5/4/2016	WS- 003000	Cooler	2	In hallway adjacent to room 204	WT-042916-3017- A	< 1	WT-042916-3017- B	< 1			

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at

B - Second draw sample is collected after a 60 second flush at that device after the