



CW Harris ES Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-013150	8/8/2018	8/8/2019	Ground Floor	Health Suite	In health suite A119	WF-08082018-013150	8/17/2018	FT-FY19-082018-013150-A	< 1	FT-FY19-082018-013150-B	< 1
WS-013151	8/8/2018	8/8/2019	Ground Floor	Cooler	In hallway adjacent to room A116 High Left	WF-08082018-013151	8/17/2018	FT-FY19-082018-013151-A	< 1	FT-FY19-082018-013151-B	< 1
WS-013152	8/8/2018	8/8/2019	Ground Floor	Cooler	In hallway adjacent to room A116 Low Right	WF-08082018-013152	8/17/2018	FT-FY19-082018-013152-A	< 1	FT-FY19-082018-013152-B	< 1
WS-013153	8/8/2018	8/8/2019	Ground Floor	Cooler	In hallway adjacent to room A116 High Left	WF-08082018-013153	8/17/2018	FT-FY19-082018-013153-A	< 1	FT-FY19-082018-013153-B	< 1
WS-013154	8/8/2018	8/8/2019	Ground Floor	Cooler	In hallway adjacent to room A116 Low Right	WF-08082018-013154	8/17/2018	FT-FY19-082018-013154-A	< 1	FT-FY19-082018-013154-B	< 1
WS-013161	8/8/2018	8/8/2019	Ground Floor	Bathroom	In bathroom in classroom B102	WF-08082018-013161	8/17/2018	FT-FY19-082018-013161-A	< 1	FT-FY19-082018-013161-B	< 1
WS-013162	8/8/2018	8/8/2019	Ground Floor	Bathroom	In bathroom in classroom B112	WF-08082018-013162	8/17/2018	FT-FY19-082018-013162-A	< 1	FT-FY19-082018-013162-B	< 1
WS-013163	8/8/2018	8/8/2019	Ground Floor	Bathroom	In bathroom in classroom B103	WF-08082018-013163	8/17/2018	FT-FY19-082018-013163-A	< 1	FT-FY19-082018-013163-B	< 1
WS-013164	8/8/2018	8/8/2019	Ground Floor	Bathroom	In bathroom in classroom B111	WF-08082018-013164	8/17/2018	FT-FY19-082018-013164-A	< 1	FT-FY19-082018-013164-B	< 1
WS-013165	8/8/2018	8/8/2019	Ground Floor	Bathroom	In bathroom in classroom B104	WF-08082018-013165	8/17/2018	FT-FY19-082018-013165-A	< 1	FT-FY19-082018-013165-B	< 1
WS-013166	8/8/2018	8/8/2019	Ground Floor	Bathroom	In bathroom in classroom B110	WF-08082018-013166	8/17/2018	FT-FY19-082018-013166-A	< 1	FT-FY19-082018-013166-B	< 1
WS-013167	8/8/2018	8/8/2019	Ground Floor	Bathroom	In bathroom in classroom B105	WF-08082018-013167	8/17/2018	FT-FY19-082018-013167-A	< 1	FT-FY19-082018-013167-B	< 1
WS-013169	8/22/2018	8/22/2019	Ground Floor	Bathroom	In bathroom in classroom B106	WF-08222018-013169	8/30/2018	FT-FY19-082018-013169-A	< 1	FT-FY19-082018-013169-B	< 1
WS-013170	8/22/2018	8/22/2019	Ground Floor	Bathroom	In bathroom in classroom B107	WF-08222018-013170	8/30/2018	FT-FY19-082018-013170-A	< 1	FT-FY19-082018-013170-B	< 1
WS-013173	8/8/2018	8/8/2019	Ground Floor	Cooler	In hallway across from C115	WF-08082018-013173	8/17/2018	FT-FY19-082018-013173-A	< 1	FT-FY19-082018-013173-B	< 1
WS-013174	8/8/2018	8/8/2019	Ground Floor	Cooler	In hallway across from C115	WF-08082018-013174	8/17/2018	FT-FY19-082018-013174-A	< 1	FT-FY19-082018-013174-B	< 1
WS-013178	8/22/2018	8/22/2019	Ground Floor	Bathroom	In classroom B101	WF-08222018-013178	8/30/2018	FT-FY19-082018-013178-A	< 1	FT-FY19-082018-013178-B	< 1
WS-013179	8/22/2018	8/22/2019	Ground Floor	Bathroom	In classroom B113	WF-08222018-013179	8/30/2018	FT-FY19-082018-013179-A	< 1	FT-FY19-082018-013179-B	< 1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation									
Record ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS-013158	Ground Floor	Food Prep Sink	In kitchen	8/17/2018	FT-FY19-082018-013158-A	< 1	FT-FY19-082018-013158-B	< 1	