



# Capitol Hill Montessori @ Meyer Lead Water Test Results



## FY20 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 010547	8/13/2019	8/13/2020	Ground Floor	Classroom Faucet	In classroom G-13	WF-08132019-010547	10/18/2019	FT-FY20-102019-010547-A	<1	FT-FY20-102019-010547-B	<1
WS- 012047	8/13/2019	8/13/2020	Ground Floor	Classroom Faucet	In classroom G-26	WF-08132019-012047	10/18/2019	FT-FY20-102019-012047-A	<1	FT-FY20-102019-012047-B	<1
WS- 012048	6/10/2019	6/10/2020	Ground Floor	Cooler	In hallway across from room G15	WF-06102019-012048	10/18/2019	FT-FY20-102019-012048-A	<1	FT-FY20-102019-012048-B	<1
WS- 012049	6/10/2019	6/10/2020	Ground Floor	Cooler	In hallway adjacent to the restroom	WF-06102019-012049	10/18/2019	FT-FY20-102019-012049-A	<1	FT-FY20-102019-012049-B	<1
WS- 012050	8/13/2019	8/13/2020	Ground Floor	Classroom Faucet	In classroom G05	WF-08132019-012050	10/18/2019	FT-FY20-102019-012050-A	<1	FT-FY20-102019-012050-B	<1
WS- 012066	6/10/2019	6/10/2020	1	Cooler	In hallway adjacent to room 143	WF-06102019-012066	10/18/2019	FT-FY20-102019-012066-A	<1	FT-FY20-102019-012066-B	<1
WS- 012068	6/10/2019	6/10/2020	1	Cooler	In health suite	WF-06102019-012068	10/18/2019	FT-FY20-102019-012068-A	<1	FT-FY20-102019-012068-B	<1
WS- 012069	8/13/2019	8/13/2020	Ground Floor	Classroom Faucet	In classroom G19	WF-08132019-012069	10/18/2019	FT-FY20-102019-012069-A	<1	FT-FY20-102019-012069-B	<1
WS- 012070	6/10/2019	6/10/2020	1	Break Room	In room 105 parent resource center	WF-06102019-012070	10/18/2019	FT-FY20-102019-012070-A	<1	FT-FY20-102019-012070-B	<1
WS- 012071	6/10/2019	6/10/2020	1	Cooler	In hallway adjacent to restroom	WF-06102019-012071	10/18/2019	FT-FY20-102019-012071-A	<1	FT-FY20-102019-012071-B	<1
WS- 012074	6/10/2019	6/10/2020	1	Cooler	In hallway adjacent to room 115	WF-06102019-012074	10/18/2019	FT-FY20-102019-012074-A	<1	FT-FY20-102019-012074-B	<1
WS- 012077	6/10/2019	6/10/2020	2	Cooler	In hallway adjacent to restroom	WF-06102019-012077	10/18/2019	FT-FY20-102019-012077-A	<1	FT-FY20-102019-012077-B	<1
WS- 012138	6/10/2019	6/10/2020	Ground Floor	Cooler	In classroom G13	WF-06102019-012138	10/18/2019	FT-FY20-102019-012138-A	<1	FT-FY20-102019-012138-B	<1
WS- 012139	8/13/2019	8/13/2020	Ground Floor	Classroom Faucet	In room G12	WF-08132019-012139	10/18/2019	FT-FY20-102019-012139-A	<1	FT-FY20-102019-012139-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012072	8/13/2019	8/13/2020	1	Food Prep Sink	In kitchen Left	WF-08132019-012072	10/18/2019	FT-FY20-102019-012072-A	<1	FT-FY20-102019-012072-B	<1