



Cardozo EC Lead Water Test Results



FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation												
RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 004123	6/26/2017	6/26/2018	3	Cooler	In hallway across from 3502	Right Low	WF-62017-004123	11/29/2017	FT-FY18-62017-004123-A	<1	FT-FY18-62017-004123-B	<1
WS- 004128	6/26/2017	6/26/2018	Basement	Cooler	On LT level, In gym hallway across from girls' locker room LT55	Left High	WF-62017-004128	11/29/2017	FT-FY18-62017-004128-A	<1	FT-FY18-62017-004128-B	<1
WS- 004131	6/26/2017	6/26/2018	Basement	Cooler	On LT level, In gym hallway across from custodial closet LT58	Right Low	WF-62017-004131	11/29/2017	FT-FY18-62017-004131-A	<1	FT-FY18-62017-004131-B	<1
WS- 004137	6/26/2017	6/26/2018	Basement	Cooler	On LT level, in LT410 (pool)	Right Low	WF-62017-004137	11/29/2017	FT-FY18-62017-004137-A	<1	FT-FY18-62017-004137-B	<1
WS- 004139	7/7/2017	7/7/2018	Basement	Cooler	In stadium locker room		WF-72017-004139	11/29/2017	FT-FY18-72017-004139-A	<1	FT-FY18-72017-004139-B	<1
WS- 004807	6/26/2017	6/26/2018	Basement	Cooler	In stadium locker room east side		WF-62017-004807	11/29/2017	FT-FY18-62017-004807-A	<1	FT-FY18-62017-004807-B	<1
WS- 008323	6/26/2017	6/26/2018	Ground Floor	Health Suite	On C level, in health suite C140		WF-62017-008323	11/29/2017	FT-FY18-62017-008323-A	<1	FT-FY18-62017-008323-B	<1
WS- 008326	6/26/2017	6/26/2018	Ground Floor	Health Suite	On C level, in health suite C146		WF-62017-008326	11/29/2017	FT-FY18-62017-008326-A	<1	FT-FY18-62017-008326-B	<1
WS- 008328	6/26/2017	6/26/2018	Ground Floor	Health Suite	On C level, in health suite C149		WF-62017-008328	11/29/2017	FT-FY18-62017-008328-A	<1	FT-FY18-62017-008328-B	<1
WS- 008332	6/26/2017	6/26/2018	Ground Floor	Cooler	On C level, in hallway across from room C205	Left High	WF-62017-008332	11/29/2017	FT-FY18-62017-008332-A	<1	FT-FY18-62017-008332-B	<1
WS- 008337	6/26/2017	6/26/2018	Ground Floor	Ice Maker	On C level, in kitchen C122 in room C118 (ice maker)		WF-62017-008337	11/29/2017	FT-FY18-62017-008337-A	<1	FT-FY18-62017-008337-B	<1
WS- 008369	6/26/2017	6/26/2018	1	Break Room	In staff lounge 1304		WF-62017-008369	11/29/2017	FT-FY18-62017-008369-A	<1	FT-FY18-62017-008369-B	<1
WS- 008395	6/26/2017	6/26/2018	1	Cooler	In hallway across from room 1603	Left High	WF-62017-008395	11/29/2017	FT-FY18-62017-008395-A	<1	FT-FY18-62017-008395-B	<1
WS- 008408	6/26/2017	6/26/2018	1	Break Room	In staff lounge 1611		WF-62017-008408	11/29/2017	FT-FY18-62017-008408-A	<1	FT-FY18-62017-008408-B	<1
WS- 008468	6/26/2017	6/26/2018	3	Cooler	In hallway adjacent to room 3204	Low	WF-62017-008468	11/29/2017	FT-FY18-62017-008468-A	<1	FT-FY18-62017-008468-B	<1

Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation									
RECORD ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 008335	Ground Floor	Food Prep Sink	On C level, in kitchen room C122 west wall	11/29/2017	FT-FY18-102017-008335-A	<1	FT-FY18-102017-008335-B	<1	