



# Chevy Chase CC Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

| Record ID  | Filter Installed Date | Filter Expiration Date | Floor    | Device Type | Device Location                       | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID    | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID    | FT Final Result - 2nd Draw (ppb) |
|------------|-----------------------|------------------------|----------|-------------|---------------------------------------|---------------------|---------------|-------------------------|----------------------------------|-------------------------|----------------------------------|
| WS- 010051 | 4/24/2018             | 4/24/2019              | Basement | Cooler      | In hallway adjacent to game room      | WF-04242018-010051  | 2/13/2019     | FT-FY19-022019-010051-A | <1                               | FT-FY19-022019-010051-B | <1                               |
| WS- 010052 | 4/24/2018             | 4/24/2019              | Basement | Cooler      | In hallway adjacent to exit/game room | WF-04242018-010052  | 2/13/2019     | FT-FY19-022019-010052-A | <1                               | FT-FY19-022019-010052-B | <1                               |
| WS- 010053 | 4/24/2018             | 4/24/2019              | 1        | Cooler      | In hallway adjacent to room 116       | WF-04242018-010053  | 2/13/2019     | FT-FY19-022019-010053-A | <1                               | FT-FY19-022019-010053-B | <1                               |
| WS- 010054 | 4/24/2018             | 4/24/2019              | 1        | Cooler      | In hallway adjacent to room 114       | WF-04242018-010054  | 2/13/2019     | FT-FY19-022019-010054-A | <1                               | FT-FY19-022019-010054-B | <1                               |
| WS- 010059 | 4/24/2018             | 4/24/2019              | 1        | Cooler      | In classroom 105                      | WF-04242018-010059  | 2/13/2019     | FT-FY19-022019-010059-A | <1                               | FT-FY19-022019-010059-B | <1                               |
| WS- 010060 | 4/24/2018             | 4/24/2019              | 2        | Cooler      | In hallway adjacent to restroom       | WF-04242018-010060  | 2/13/2019     | FT-FY19-022019-010060-A | <1                               | FT-FY19-022019-010060-B | <1                               |
| WS- 010061 | 4/24/2018             | 4/24/2019              | 2        | Cooler      | In hallway adjacent to art room       | WF-04242018-010061  | 2/13/2019     | FT-FY19-022019-010061-A | <1                               | FT-FY19-022019-010061-B | <1                               |

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation

| Record ID  | Filter Installed Date | Filter Expiration Date | Floor | Device Type    | Device Location | Water Filter's Name | Date Analyzed | 1st Draw - Sample ID    | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID    | FT Final Result - 2nd Draw (ppb) |
|------------|-----------------------|------------------------|-------|----------------|-----------------|---------------------|---------------|-------------------------|----------------------------------|-------------------------|----------------------------------|
| WS- 010055 | 4/24/2018             | 4/24/2019              | 1     | Food Prep Sink | In kitchen      | WF-04242018-010055  | 2/13/2019     | FT-FY19-022019-010055-A | <1                               | FT-FY19-022019-010055-B | <1                               |