



CHEVY CHASE COMM LEAD WATER TEST RESULTS May 16th, 2016



| | Building Location | Sample Collected Date | Water Source ID | Device Type | Floor | Device Location | 1st Draw - Sample ID | Final Result - 1st Draw (ug/L) | 2nd Draw - Sample ID | Final Result - 2nd Draw (ug/L) | Remediation | Retest Date | Retest 1st Draw | Retest 2nd Draw |
|----|------------------------------|-----------------------|-----------------|-------------|--------------|--|----------------------|--------------------------------|----------------------|--------------------------------|--|-------------|-----------------|-----------------|
| 1 | CHEVY CHASE COMMUNITY CENTER | 5/19/2016 | WS- 010049 | Utility | Basement | In boiler room 015 (water source) | WT-042916-10066- A | 5.7 | WT-042916-10066- B | < 2 | | | | |
| 2 | CHEVY CHASE COMMUNITY CENTER | 5/19/2016 | WS- 010050 | Cooler | Basement | In hallway adjacent to men's dressing room 018 | WT-042916-10067- A | 3.2 | WT-042916-10067- B | 3.6 | | | | |
| 3 | CHEVY CHASE COMMUNITY CENTER | 5/19/2016 | WS- 010051 | Cooler | Basement | In hallway adjacent to game room | WT-042916-10068- A | < 2 | WT-042916-10068- B | < 2 | | | | |
| 4 | CHEVY CHASE COMMUNITY CENTER | 5/19/2016 | WS- 010052 | Cooler | Basement | In hallway adjacent to exit/game room | WT-042916-10069- A | < 2 | WT-042916-10069- B | < 2 | | | | |
| 5 | CHEVY CHASE COMMUNITY CENTER | 5/19/2016 | WS- 010053 | Cooler | 1 | In hallway adjacent to room 116 | WT-042916-10070- A | < 2 | WT-042916-10070- B | < 2 | | | | |
| 6 | CHEVY CHASE COMMUNITY CENTER | 5/19/2016 | WS- 010054 | Cooler | 1 | In hallway adjacent to room 114 | WT-042916-10071- A | < 2 | WT-042916-10071- B | < 2 | | | | |
| 7 | CHEVY CHASE COMMUNITY CENTER | 5/19/2016 | WS- 010055 | Kitchen | 1 | In kitchen, sink | WT-042916-10072- A | < 2 | WT-042916-10072- B | < 2 | | | | |
| 8 | CHEVY CHASE COMMUNITY CENTER | 5/19/2016 | WS- 010057 | Classroom | 1 | In room 105 Left | WT-042916-10074- A | < 2 | WT-042916-10074- B | < 2 | | | | |
| 9 | CHEVY CHASE COMMUNITY CENTER | 5/19/2016 | WS- 010058 | Classroom | 1 | In room 105 Right | WT-042916-10075- A | < 2 | WT-042916-10075- B | < 2 | | | | |
| 10 | CHEVY CHASE COMMUNITY CENTER | 5/19/2016 | WS- 010059 | Cooler | 1 | In room 105 | WT-042916-10076- A | < 2 | WT-042916-10076- B | 2.3 | | | | |
| 11 | CHEVY CHASE COMMUNITY CENTER | 5/19/2016 | WS- 010060 | Cooler | 2 | In hallway 215 | WT-042916-10077- A | < 2 | WT-042916-10077- B | < 2 | | | | |
| 12 | CHEVY CHASE COMMUNITY CENTER | 5/19/2016 | WS- 010061 | Cooler | 2 | In hallway adjacent to room 203 | WT-042916-10078- A | < 2 | WT-042916-10078- B | < 2 | | | | |
| 13 | CHEVY CHASE COMMUNITY CENTER | 5/19/2016 | WS- 010062 | Classroom | 2 | In room 210 Right | WT-042916-10079- A | < 2 | WT-042916-10079- B | < 2 | | | | |
| 14 | CHEVY CHASE COMMUNITY CENTER | 5/19/2016 | WS- 010063 | Classroom | 2 | In room 210 Mid | WT-042916-10080- A | < 2 | WT-042916-10080- B | < 2 | | | | |
| 15 | CHEVY CHASE COMMUNITY CENTER | 5/19/2016 | WS- 010064 | Classroom | 2 | In room 210 Left | WT-042916-10081- A | < 2 | WT-042916-10081- B | < 2 | | | | |
| 16 | CHEVY CHASE COMMUNITY CENTER | 5/19/2016 | WS- 010065 | Fountain | Ground Floor | In exterior adjacent to basketball court | WT-042916-10082- A | 25.5 | WT-042916-10082- B | 8.8 | Filter will be installed and then retested | | | |

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.