



Chevy Chase RC Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012535	4/25/2018	4/25/2019	1	Cooler	In hallway adjacent to mechanical room	High	WF-04252018-012535	2/11/2019	FT-FY19-022019-012535-A	<1	FT-FY19-022019-012535-B	<1
WS- 012536	4/25/2018	4/25/2019	1	Cooler	In hallway adjacent to mechanical room	Low	WF-04252018-012536	2/11/2019	FT-FY19-022019-012536-A	<1	FT-FY19-022019-012536-B	<1
WS- 012539	4/25/2018	4/25/2019	1	Ice Maker	In kitchen (ice maker)		WF-04252018-012539	2/11/2019	FT-FY19-022019-012539-A	<1	FT-FY19-022019-012539-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012537	4/25/2018	4/25/2019	1	Food Prep Sink	In kitchen		WF-04252018-012537	2/11/2019	FT-FY19-022019-012537-A	<1	FT-FY19-022019-012537-B	<1