



CHEVY CHASE REC LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	CHEVY CHASE RECREATION CENTER	5/19/2016	WS- 012529	Fountain	Ground Floor	Exterior, adjacent to slide (bottom tap)	Low WT-042916-12546- A	< 2	WT-042916-12546- B	< 2				
2	CHEVY CHASE RECREATION CENTER	5/19/2016	WS- 012530	Fountain	Ground Floor	Exterior, adjacent to slide	High WT-042916-12547- A	< 2	WT-042916-12547- B	< 2				
3	CHEVY CHASE RECREATION CENTER	5/19/2016	WS- 012531	Fountain	Ground Floor	Exterior, adjacent to slide	Low WT-042916-12548- A	< 2	WT-042916-12548- B	< 2				
4	CHEVY CHASE RECREATION CENTER	5/19/2016	WS- 012532	Fountain	Ground Floor	Exterior, across from restroom (bottom tap)	Low WT-042916-12549- A	< 2	WT-042916-12549- B	< 2				
5	CHEVY CHASE RECREATION CENTER	5/19/2016	WS- 012533	Fountain	Ground Floor	Exterior, across from restroom	High WT-042916-12550- A	< 2	WT-042916-12550- B	< 2				
6	CHEVY CHASE RECREATION CENTER	5/19/2016	WS- 012534	Fountain	Ground Floor	Exterior, across from restroom	Low WT-042916-12551- A	< 2	WT-042916-12551- B	< 2				
7	CHEVY CHASE RECREATION CENTER	5/19/2016	WS- 012535	Cooler	1	In hallway adjacent to mechanical room	High WT-042916-12552- A	< 2	WT-042916-12552- B	< 2				
8	CHEVY CHASE RECREATION CENTER	5/19/2016	WS- 012536	Cooler	1	In hallway adjacent to mechanical room	Low WT-042916-12553- A	< 2	WT-042916-12553- B	< 2				
9	CHEVY CHASE RECREATION CENTER	5/19/2016	WS- 012537	Kitchen	1	In kitchen across from front entrance	WT-042916-12554- A	< 2	WT-042916-12554- B	< 2				
10	CHEVY CHASE RECREATION CENTER	5/19/2016	WS- 012538	Utility	1	In mechanical room (water source)	WT-042916-12555- A	< 2	WT-042916-12555- B	< 2				
11	CHEVY CHASE RECREATION CENTER	5/19/2016	WS- 012539	Kitchen	1	In refrigerator freezer (ice maker)	WT-042916-12556- A	< 1	WT-042916-12556- B	< 2				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.