



# Coolidge HS Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012182	8/16/2018	8/16/2019	Ground Floor	Cooler	In breezeway adjacent to T01 unisex toilet	High Left	WF-08162018-012182	8/28/2018	FT-FY19-082018-012182-A	< 1	FT-FY19-082018-012182-B	< 1
WS- 012183	8/16/2018	8/16/2019	Ground Floor	Cooler	In breezeway adjacent to T01 unisex toilet	Low Right	WF-08162018-012183	8/28/2018	FT-FY19-082018-012183-A	< 1	FT-FY19-082018-012183-B	< 1
WS- 012184	8/16/2018	8/16/2019	Ground Floor	Cooler	In breezeway adjacent to T01 unisex toilet	High Left	WF-08162018-012184	8/28/2018	FT-FY19-082018-012184-A	< 1	FT-FY19-082018-012184-B	< 1
WS- 012185	8/16/2018	8/16/2019	Ground Floor	Cooler	In breezeway adjacent to T01 unisex toilet	Low Right	WF-08162018-012185	8/28/2018	FT-FY19-082018-012185-A	< 1	FT-FY19-082018-012185-B	< 1
WS- 012186	8/16/2018	8/16/2019	Ground Floor	Cooler	In breezeway adjacent to T02 unisex toilet	High Left	WF-08162018-012186	8/28/2018	FT-FY19-082018-012186-A	< 1	FT-FY19-082018-012186-B	< 1
WS- 012187	8/16/2018	8/16/2019	Ground Floor	Cooler	In breezeway adjacent to T02 unisex toilet	Low Right	WF-08162018-012187	8/28/2018	FT-FY19-082018-012187-A	< 1	FT-FY19-082018-012187-B	< 1
WS- 012188	8/16/2018	8/16/2019	Ground Floor	Cooler	In breezeway adjacent to T02 unisex toilet	High Left	WF-08162018-012188	8/28/2018	FT-FY19-082018-012188-A	< 1	FT-FY19-082018-012188-B	< 1
WS- 012189	8/16/2018	8/16/2019	Ground Floor	Cooler	In breezeway adjacent to T02 unisex toilet	Low Right	WF-08162018-012189	8/28/2018	FT-FY19-082018-012189-A	< 1	FT-FY19-082018-012189-B	< 1
WS- 012190	8/16/2018	8/16/2019	Ground Floor	Cooler	In kitchen in back room adjacent to K01T unisex toilet	High Left	WF-08162018-012190	8/28/2018	FT-FY19-082018-012190-A	< 1	FT-FY19-082018-012190-B	< 1
WS- 012191	8/16/2018	8/16/2019	Ground Floor	Cooler	In kitchen in back room adjacent to K01T unisex toilet	Low Right	WF-08162018-012191	8/28/2018	FT-FY19-082018-012191-A	< 1	FT-FY19-082018-012191-B	< 1
WS- 012205	8/16/2018	8/16/2019	Basement	Cooler	In gym adjacent to boys' locker room		WF-08162018-012205	8/28/2018	FT-FY19-082018-012205-A	< 1	FT-FY19-082018-012205-B	< 1
WS- 012207	8/16/2018	8/16/2019	Basement	Cooler	In gym adjacent to stairwell 3		WF-08162018-012207	8/28/2018	FT-FY19-082018-012207-A	3.4	FT-FY19-082018-012207-B	2.3
WS- 012210	8/16/2018	8/16/2019	Basement	Cooler	In girls' locker room (new building)		WF-08162018-012210	8/28/2018	FT-FY19-082018-012210-A	< 1	FT-FY19-082018-012210-B	< 1
WS- 012212	8/16/2018	8/16/2019	Basement	Cooler	In gym adjacent to stairwell 2		WF-08162018-012212	8/28/2018	FT-FY19-082018-012212-A	< 1	FT-FY19-082018-012212-B	< 1
WS- 012213	8/16/2018	8/16/2019	Ground Floor	Cooler	In the Frank R. William activity center adjacent to door 172		WF-08162018-012213	8/28/2018	FT-FY19-082018-012213-A	< 1	FT-FY19-082018-012213-B	< 1
WS- 012216	8/16/2018	8/16/2019	Ground Floor	Cooler	In the Frank R. William activity center adjacent to door 174	Left	WF-08162018-012216	8/28/2018	FT-FY19-082018-012216-A	< 1	FT-FY19-082018-012216-B	< 1
WS- 012224	8/16/2018	8/16/2019	Ground Floor	Health Suite	In health suite in exam room 3		WF-08162018-012224	8/28/2018	FT-FY19-082018-012224-A	< 1	FT-FY19-082018-012224-B	< 1
WS- 012225	8/16/2018	8/16/2019	Ground Floor	Health Suite	In health suite in exam room 5		WF-08162018-012225	8/28/2018	FT-FY19-082018-012225-A	< 1	FT-FY19-082018-012225-B	< 1
WS- 012226	8/16/2018	8/16/2019	Ground Floor	Health Suite	In health suite in exam room 4		WF-08162018-012226	8/28/2018	FT-FY19-082018-012226-A	< 1	FT-FY19-082018-012226-B	< 1
WS- 012227	8/16/2018	8/16/2019	Ground Floor	Break Room	In health suite in break room 6 coffee		WF-08162018-012227	8/28/2018	FT-FY19-082018-012227-A	< 1	FT-FY19-082018-012227-B	< 1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation									
Record ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 012192	Ground Floor	Food Prep Sink	In kitchen adjacent to exit	8/28/2018	FT-FY19-082018-012192-A	< 1	FT-FY19-082018-012192-B	< 1	