



# COOLIDGE LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw	
1	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012255	Cooler	3	In hallway adjacent to stairway 5	WT-042916-12272- A	< 1	WT-042916-12272- B	< 1				
2	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012254	Cooler	3	In hallway adjacent to stairway 6	WT-042916-12271- A	< 1	WT-042916-12271- B	< 1				
3	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012253	Cooler	3	In hallway adjacent staircase 4	WT-042916-12270- A	< 1	WT-042916-12270- B	< 1				
4	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012252	Cooler	3	In hallway adjacent staircase 3	WT-042916-12269- A	< 1	WT-042916-12269- B	< 1				
5	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012251	Cooler	2	In hallway adjacent to stairway 5	WT-042916-12268- A	< 1	WT-042916-12268- B	< 1				
6	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012250	Cooler	2	In hallway adjacent to stairway 6	WT-042916-12267- A	< 1	WT-042916-12267- B	< 1				
7	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012249	Cooler	2	In hallway adjacent to stairway 4	WT-042916-12266- A	< 1	WT-042916-12266- B	< 1				
8	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012248	Cooler	2	In hallway adjacent to stairway 3	WT-042916-12265- A	< 1	WT-042916-12265- B	< 1				
9	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012239	Classroom	1	In classroom 107 sink 1	WT-042916-12256- A	3.4	WT-042916-12256- B	< 1				
10	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012238	Classroom	1	In room 127 clockwise sink 10	WT-042916-12255- A	41	WT-042916-12255- B	2	Filter will be installed and then retested			
11	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012237	Classroom	1	In room 127 clockwise sink 9	WT-042916-12254- A	58	WT-042916-12254- B	8.3	Filter will be installed and then retested			
12	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012236	Classroom	1	In room 127 clock wise sink 8	WT-042916-12253- A	4.6	WT-042916-12253- B	< 1				
13	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012235	Classroom	1	In classroom 127 sink 7	WT-042916-12252- A	1.4	WT-042916-12252- B	< 1				
14	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012234	Classroom	1	In classroom 127 sink 6	WT-042916-12251- A	< 1	WT-042916-12251- B	< 1				
15	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012233	Classroom	1	In classroom 127 sink 5	WT-042916-12250- A	4.7	WT-042916-12250- B	< 1				
16	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012232	Classroom	1	In classroom 127 sink 4	WT-042916-12249- A	1.3	WT-042916-12249- B	< 1				
17	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012231	Classroom	1	In classroom 127 sink 3	WT-042916-12248- A	4.1	WT-042916-12248- B	< 1				
18	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012230	Classroom	1	In classroom 127 sink 2	WT-042916-12247- A	60	WT-042916-12247- B	2.2	Filter will be installed and then retested			
19	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012229	Classroom	1	In classroom 127 sink 1	WT-042916-12246- A	76	WT-042916-12246- B	11	Filter will be installed and then retested			
20	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012228	Health Suite	1	In laboratory room 2673	WT-042916-12245- A	< 1	WT-042916-12245- B	< 1				
21	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012227	Health Suite	1	In break room 2678	WT-042916-12244- A	< 1	WT-042916-12244- B	< 1				
22	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012226	Health Suite	1	In exam room 2676	WT-042916-12243- A	< 1	WT-042916-12243- B	< 1				
23	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012225	Health Suite	1	In exam room 2674	WT-042916-12242- A	< 1	WT-042916-12242- B	< 1				
24	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012224	Health Suite	1	In exam room 2672	WT-042916-12241- A	< 1	WT-042916-12241- B	< 1				
25	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012223	Classroom	1	In art classroom 105 sink 2	WT-042916-12240- A	67	WT-042916-12240- B	72	Filter will be installed and then retested			
26	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012222	Classroom	1	In art classroom 105 sink 1	WT-042916-12239- A	3.4	WT-042916-12239- B	1.9				
27	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012221	Cooler	1	In hallway adjacent to stairway 3	WT-042916-12238- A	< 1	WT-042916-12238- B	1.4				
28	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012219	Cooler	1	In hallway adjacent to stairway 6	WT-042916-12236- A	< 1	WT-042916-12236- B	< 1				
29	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012218	Cooler	1	In hallway adjacent to stairway 4	WT-042916-12235- A	< 1	WT-042916-12235- B	< 1				
30	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012216	Cooler	Ground Floor	In the Frank's r Williams activity center adjacent to door 174	WT-042916-12233- A	2.2	WT-042916-12233- B	< 1				
31	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012215	Fountain	Ground Floor	In frank r William activity center adjacent to door 173	WT-042916-12232- A	5.6	WT-042916-12232- B	2.5				
32	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012214	Cooler	Ground Floor	In frank r William activity center adjacent to door 173	WT-042916-12231- A	1.4	WT-042916-12231- B	2.6				
33	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012213	Cooler	Ground Floor	In frank r William activity center adjacent to door 172	WT-042916-12230- A	< 1	WT-042916-12230- B	< 1				
34	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012212	Cooler	Basement	In gymnasium adjacent to stairway 2	WT-042916-12229- A	< 1	WT-042916-12229- B	< 1				
35	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012211	Cooler	Basement	In girl basketball locker room	WT-042916-12228- A	< 1	WT-042916-12228- B	< 1				
36	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012210	Cooler	Basement	In girls locker room (new building)	WT-042916-12227- A	1.4	WT-042916-12227- B	2.1				
37	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012209	Cooler	Basement	In hallway adjacent to girl locker room	WT-042916-12226- A	< 1	WT-042916-12226- B	< 1				
38	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012208	Cooler	Basement	In boys locker room	WT-042916-12225- A	< 1	WT-042916-12225- B	< 1				
39	COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012207	Cooler	Basement	In gymnasium north side adjacent to stairway	WT-042916-12224- A	4.1	WT-042916-12224- B	< 1				



# COOLIDGE LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
40 COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012206	Cooler	Basement	In boys varisty basketball locker room	WT-042916-12223- A	520	WT-042916-12223- B	760	Filter will be installed and then retested			
41 COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012205	Cooler	Basement	In gymnasium	WT-042916-12222- A	1.9	WT-042916-12222- B	< 1				
42 COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012204	Cooler	Basement	In hallway adjacent to weight room B105	WT-042916-12221- A	< 1	WT-042916-12221- B	< 1				
43 COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012203	Cooler	Ground Floor	In boys gymnasium	WT-042916-12220- A	< 1	WT-042916-12220- B	< 1				
44 COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012202	Cooler	Ground Floor	In hallway adjacent to armory	WT-042916-12219- A	< 1	WT-042916-12219- B	< 1				
45 COOLIDGE HIGH SCHOOL	5/18/2016	WS- 012201	Cooler	Ground Floor	In girls gym adjacent to Cafeteria	WT-042916-12218- A	< 1	WT-042916-12218- B	< 1				
46 COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012200	Cooler	Ground Floor	In cafeteria adjacent to kitchen	WT-042916-12217- A	21	WT-042916-12217- B	1.5	Filter will be installed and then retested			
47 COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012199	Kitchen	Ground Floor	In kitchen clockwise 2nd sink	WT-042916-12216- A	< 1	WT-042916-12216- B	< 1				
48 COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012198	Kitchen	Ground Floor	In kitchen clockwise 1st sink	WT-042916-12215- A	1.8	WT-042916-12215- B	< 1				
49 COOLIDGE HIGH SCHOOL	5/17/2016	WS- 012197	Utility	Basement	Basement Sink	WT-042916-12214- A	1.6	WT-042916-12214- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.