



Davis Swing Space Lead in Water Test Results

FY24 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 007499	4/19/2023	4/19/2024	1	Combo Fountain	In classroom c109	WF-04192023-007499	1/10/2024	FT-FY24-11272023-007499-A	2.3	FT-FY24-11272023-007499-B	<1
WS- 007500	4/19/2023	4/19/2024	2	Cooler	In hallway adjacent to janitors closet b201c	WF-04192023-007500	1/10/2024	FT-FY24-11272023-007500-A	<1	FT-FY24-11272023-007500-B	<1
WS- 007501	4/19/2023	4/19/2024	2	Cooler	In hallway adjacent to classroom 204	WF-04192023-007501	1/10/2024	FT-FY24-11272023-007501-A	<1	FT-FY24-11272023-007501-B	<1
WS- 007505	4/19/2023	4/19/2024	1	Cooler	In hallway adjacent to janitors closet c108	WF-04192023-007505	1/10/2024	FT-FY24-11272023-007505-A	<1	FT-FY24-11272023-007505-B	<1
WS- 007508	11/8/2023	11/8/2024	1	Cooler	In hallway adjacent to b101c janitor closet	WF-11082023-007508	1/10/2024	FT-FY24-11272023-007508-A	<1	FT-FY24-11272023-007508-B	<1
WS- 007518	4/19/2023	4/19/2024	1	Combo Fountain	In classroom c104	WF-04192023-007518	1/10/2024	FT-FY24-11272023-007518-A	<1	FT-FY24-11272023-007518-B	<1
WS- 007519	4/19/2023	4/19/2024	1	Combo Fountain	In classroom c102	WF-04192023-007519	1/10/2024	FT-FY24-11272023-007519-A	<1	FT-FY24-11272023-007519-B	<1
WS- 007520	4/19/2023	4/19/2024	1	Combo Fountain	In classroom c103	WF-04192023-007520	1/10/2024	FT-FY24-11272023-007520-A	<1	FT-FY24-11272023-007520-B	<1
WS- 007521	4/19/2023	4/19/2024	1	Combo Fountain	In classroom c110	WF-04192023-007521	1/10/2024	FT-FY24-11272023-007521-A	1.0	FT-FY24-11272023-007521-B	<1
WS- 007523	4/19/2023	4/19/2024	2	Bottle Filler	In hallway adjacent to classroom 204	WF-04192023-007523	1/10/2024	FT-FY24-11272023-007523-A	<1	FT-FY24-11272023-007523-B	<1
WS- 007524	4/19/2023	4/19/2024	2	Bottle Filler	In hallway adjacent to janitors closet b201c	WF-04192023-007524	1/10/2024	FT-FY24-11272023-007524-A	<1	FT-FY24-11272023-007524-B	<1
WS- 007525	11/8/2023	11/8/2024	2	Bottle Filler	In hallway across from room 207	WF-11082023-007525	1/10/2024	FT-FY24-11272023-007525-A	<1	FT-FY24-11272023-007525-B	<1
WS- 007526	4/19/2023	4/19/2024	1	Bottle Filler	In hallway adjacent to janitors closet c108	WF-04192023-007526	1/10/2024	FT-FY24-11272023-007526-A	<1	FT-FY24-11272023-007526-B	<1
WS- 007527	11/8/2023	11/8/2024	1	Bottle Filler	In hallway adjacent to b101c janitor closet	WF-11082023-007527	1/10/2024	FT-FY24-11272023-007527-A	<1	FT-FY24-11272023-007527-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 007515	12/21/2022	12/21/2023	Basement	Food Prep Sink	In kitchen third from left Right	WF-12212022-007515	1/10/2024	FT-FY24-11272023-007515-A	<1	FT-FY24-11272023-007515-B	<1