



# Deal Lead Water Test Results



## FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-011156	5/30/2017	5/30/2018	Ground Floor	Cooler	In cafeteria room NG20 Right Low	WF-52017-011156	12/8/2017	FT-FY18-52017-011156-A	<1	FT-FY18-52017-011156-B	<1
WS-011164	5/30/2017	5/30/2018	Ground Floor	Cooler	In gym NG01 Right Low	WF-52017-011164	12/8/2017	FT-FY18-52017-011164-A	<1	FT-FY18-52017-011164-B	<1
WS-011165	5/30/2017	5/30/2018	Ground Floor	Cooler	In hallway adjacent to boys' locker room NG12 Left High	WF-52017-011165	12/8/2017	FT-FY18-52017-011165-A	<1	FT-FY18-52017-011165-B	<1
WS-011170	5/30/2017	5/30/2018	Ground Floor	Combo Fountain	In classroom RG02 first clockwise from entry door	WF-52017-011170	12/8/2017	FT-FY18-52017-011170-A	<1	FT-FY18-52017-011170-B	<1
WS-011172	5/30/2017	5/30/2018	Ground Floor	Combo Fountain	In classroom RG02 third clockwise from entry door	WF-52017-011172	12/8/2017	FT-FY18-52017-011172-A	<1	FT-FY18-52017-011172-B	<1
WS-011175	5/30/2017	5/30/2018	Ground Floor	Bottle Filler	In hallway across from RG03 (bottle filler) High	WF-52017-011175	12/8/2017	FT-FY18-52017-011175-A	<1	FT-FY18-52017-011175-B	<1
WS-011179	5/30/2017	5/30/2018	1	Bottle Filler	In hallway across from room R109 (bottle filler) Left High	WF-52017-011179	12/8/2017	FT-FY18-52017-011179-A	<1	FT-FY18-52017-011179-B	<1
WS-011180	5/30/2017	5/30/2018	1	Cooler	In hallway across from room R109 Left Low	WF-52017-011180	12/8/2017	FT-FY18-52017-011180-A	<1	FT-FY18-52017-011180-B	<1
WS-011189	5/30/2017	5/30/2018	1	Combo Fountain	In classroom R102 first clockwise from entry door	WF-52017-011189	12/8/2017	FT-FY18-52017-011189-A	<1	FT-FY18-52017-011189-B	<1
WS-011197	5/30/2017	5/30/2018	1	Health Suite	In health suite	WF-52017-011197	12/8/2017	FT-FY18-52017-011197-A	<1	FT-FY18-52017-011197-B	<1
WS-011207	5/30/2017	5/30/2018	1	Cooler	In hallway adjacent to room E100 Right Low	WF-52017-011207	12/8/2017	FT-FY18-52017-011207-A	<1	FT-FY18-52017-011207-B	<1
WS-011210	5/30/2017	5/30/2018	1	Cooler	In hallway across from stairwell C2 Right Low	WF-52017-011210	12/8/2017	FT-FY18-52017-011210-A	<1	FT-FY18-52017-011210-B	<1
WS-011264	5/30/2017	5/30/2018	2	Break Room	In staff lounge C216	WF-52017-011264	12/8/2017	FT-FY18-52017-011264-A	<1	FT-FY18-52017-011264-B	<1
WS-011266	5/30/2017	5/30/2018	2	Cooler	In hallway adjacent to room E200 Left High	WF-52017-011266	12/8/2017	FT-FY18-52017-011266-A	<1	FT-FY18-52017-011266-B	<1
WS-011267	5/30/2017	5/30/2018	2	Cooler	In hallway adjacent to room E200 Right Low	WF-52017-011267	12/8/2017	FT-FY18-52017-011267-A	<1	FT-FY18-52017-011267-B	<1
WS-011495	8/9/2017	8/9/2018	1	Cooler	Annex, in hallway adjacent to room N114 Right Low	WF-82017-011495	12/8/2017	FT-FY18-82017-011495-A	<1	FT-FY18-82017-011495-B	<1

## Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-010535	Ground Floor	Food Prep Sink	In kitchen on west wall Left	12/8/2017	FT-FY18-102017-010535-A	<1	FT-FY18-102017-010535-B	<1