



Deal MS Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 011155	4/18/2018	4/18/2019	Ground Floor	Cooler	In cafeteria room NG20	High Left	WF-04182018-011155	12/28/2018	FT-FY19-122018-011155-A	<1	FT-FY19-122018-011155-B	<1
WS- 011156	4/18/2018	4/18/2019	Ground Floor	Cooler	In cafeteria room NG20	Low Right	WF-04182018-011156	12/28/2018	FT-FY19-122018-011156-A	<1	FT-FY19-122018-011156-B	<1
WS- 011157	4/18/2018	4/18/2019	Ground Floor	Cooler	In hallway adjacent to room NG20	High Left	WF-04182018-011157	12/28/2018	FT-FY19-122018-011157-A	<1	FT-FY19-122018-011157-B	<1
WS- 011158	4/18/2018	4/18/2019	Ground Floor	Cooler	In hallway adjacent to room NG20	Low Right	WF-04182018-011158	12/28/2018	FT-FY19-122018-011158-A	<1	FT-FY19-122018-011158-B	<1
WS- 011159	4/18/2018	4/18/2019	Ground Floor	Cooler	In hallway adjacent to girls' restroom	High Left	WF-04182018-011159	12/28/2018	FT-FY19-122018-011159-A	<1	FT-FY19-122018-011159-B	<1
WS- 011160	4/18/2018	4/18/2019	Ground Floor	Cooler	In hallway adjacent to girls' restroom	Low Right	WF-04182018-011160	12/28/2018	FT-FY19-122018-011160-A	<1	FT-FY19-122018-011160-B	<1
WS- 011161	4/18/2018	4/18/2019	Ground Floor	Cooler	In gym NG01	High Left	WF-04182018-011161	12/28/2018	FT-FY19-122018-011161-A	<1	FT-FY19-122018-011161-B	<1
WS- 011162	4/18/2018	4/18/2019	Ground Floor	Cooler	In gym NG01	Low Left	WF-04182018-011162	12/28/2018	FT-FY19-122018-011162-A	<1	FT-FY19-122018-011162-B	<1
WS- 011165	4/18/2018	4/18/2019	Ground Floor	Cooler	In hallway adjacent to boys' locker room NG12	High Left	WF-04182018-011165	12/28/2018	FT-FY19-122018-011165-A	<1	FT-FY19-122018-011165-B	<1
WS- 011168	4/18/2018	4/18/2019	Ground Floor	Combo Fountain	In classroom RG02 second clockwise from entry door		WF-04182018-011168	12/28/2018	FT-FY19-122018-011168-A	<1	FT-FY19-122018-011168-B	<1
WS- 011170	4/18/2018	4/18/2019	Ground Floor	Combo Fountain	In classroom RG02 first clockwise from entry door		WF-04182018-011170	12/28/2018	FT-FY19-122018-011170-A	<1	FT-FY19-122018-011170-B	<1
WS- 011172	4/18/2018	4/18/2019	Ground Floor	Combo Fountain	In classroom RG02 third clockwise from entry door		WF-04182018-011172	12/28/2018	FT-FY19-122018-011172-A	<1	FT-FY19-122018-011172-B	<1
WS- 011174	4/18/2018	4/18/2019	Ground Floor	Combo Fountain	In classroom RG02 fourth clockwise from entry door		WF-04182018-011174	12/28/2018	FT-FY19-122018-011174-A	<1	FT-FY19-122018-011174-B	<1
WS- 011175	4/18/2018	4/18/2019	Ground Floor	Bottle Filler	In hallway across from RG03 (bottle filler)		WF-04182018-011175	12/28/2018	FT-FY19-122018-011175-A	<1	FT-FY19-122018-011175-B	<1
WS- 011176	4/18/2018	4/18/2019	Ground Floor	Cooler	In hallway across from RG03		WF-04182018-011176	12/28/2018	FT-FY19-122018-011176-A	<1	FT-FY19-122018-011176-B	<1
WS- 011177	4/18/2018	4/18/2019	Ground Floor	Bottle Filler	In hallway across from elevator (bottle filler)		WF-04182018-011177	12/28/2018	FT-FY19-122018-011177-A	<1	FT-FY19-122018-011177-B	<1
WS- 011178	4/18/2018	4/18/2019	Ground Floor	Cooler	In hallway across from elevator		WF-04182018-011178	12/28/2018	FT-FY19-122018-011178-A	<1	FT-FY19-122018-011178-B	<1
WS- 011179	4/18/2018	4/18/2019	1	Bottle Filler	In hallway across from room R109 (bottle filler)		WF-04182018-011179	12/28/2018	FT-FY19-122018-011179-A	<1	FT-FY19-122018-011179-B	<1
WS- 011180	4/18/2018	4/18/2019	1	Cooler	In hallway across from room R109	Low Left	WF-04182018-011180	12/28/2018	FT-FY19-122018-011180-A	<1	FT-FY19-122018-011180-B	<1
WS- 011181	4/18/2018	4/18/2019	1	Cooler	In hallway across from room R109	Low Right	WF-04182018-011181	12/28/2018	FT-FY19-122018-011181-A	<1	FT-FY19-122018-011181-B	<1
WS- 011182	4/18/2018	4/18/2019	1	Combo Fountain	In classroom R111	Left	WF-04182018-011182	12/28/2018	FT-FY19-122018-011182-A	<1	FT-FY19-122018-011182-B	<1
WS- 011183	4/18/2018	4/18/2019	1	Combo Fountain	In classroom R111	Right	WF-04182018-011183	12/28/2018	FT-FY19-122018-011183-A	<1	FT-FY19-122018-011183-B	<1
WS- 011186	4/18/2018	4/18/2019	1	Bottle Filler	In hallway adjacent to restrooms (bottle filler)		WF-04182018-011186	12/28/2018	FT-FY19-122018-011186-A	<1	FT-FY19-122018-011186-B	<1
WS- 011187	4/18/2018	4/18/2019	1	Cooler	In hallway adjacent to restrooms		WF-04182018-011187	12/28/2018	FT-FY19-122018-011187-A	<1	FT-FY19-122018-011187-B	<1
WS- 011189	4/18/2018	4/18/2019	1	Combo Fountain	In classroom R102 first clockwise from entry door		WF-04182018-011189	12/28/2018	FT-FY19-122018-011189-A	<1	FT-FY19-122018-011189-B	<1
WS- 011191	4/18/2018	4/18/2019	1	Combo Fountain	In classroom R102 second clockwise from entry door		WF-04182018-011191	12/28/2018	FT-FY19-122018-011191-A	<1	FT-FY19-122018-011191-B	<1
WS- 011193	4/18/2018	4/18/2019	1	Combo Fountain	In classroom R102 third clockwise from entry door		WF-04182018-011193	12/28/2018	FT-FY19-122018-011193-A	<1	FT-FY19-122018-011193-B	<1
WS- 011195	4/18/2018	4/18/2019	1	Combo Fountain	In classroom R102 fourth clockwise from entry door		WF-04182018-011195	12/28/2018	FT-FY19-122018-011195-A	<1	FT-FY19-122018-011195-B	<1
WS- 011197	4/18/2018	4/18/2019	1	Health Suite	In health suite		WF-04182018-011197	12/28/2018	FT-FY19-122018-011197-A	<1	FT-FY19-122018-011197-B	<1
WS- 011206	4/18/2018	4/18/2019	1	Cooler	In hallway adjacent to room E100	High Left	WF-04182018-011206	12/28/2018	FT-FY19-122018-011206-A	<1	FT-FY19-122018-011206-B	<1
WS- 011207	4/18/2018	4/18/2019	1	Cooler	In hallway adjacent to room E100	Low Right	WF-04182018-011207	12/28/2018	FT-FY19-122018-011207-A	<1	FT-FY19-122018-011207-B	<1
WS- 011209	4/18/2018	4/18/2019	1	Cooler	In hallway across from stairwell C2	High Left	WF-04182018-011209	12/28/2018	FT-FY19-122018-011209-A	<1	FT-FY19-122018-011209-B	<1
WS- 011210	4/18/2018	4/18/2019	1	Cooler	In hallway across from stairwell C2	Low Right	WF-04182018-011210	12/28/2018	FT-FY19-122018-011210-A	<1	FT-FY19-122018-011210-B	<1
WS- 011264	4/18/2018	4/18/2019	2	Break Room	In staff lounge C216		WF-04182018-011264	12/28/2018	FT-FY19-122018-011264-A	<1	FT-FY19-122018-011264-B	<1
WS- 011266	4/18/2018	4/18/2019	2	Cooler	In hallway adjacent to room E200	High Left	WF-04182018-011266	12/28/2018	FT-FY19-122018-011266-A	<1	FT-FY19-122018-011266-B	<1

WS-011267	4/18/2018	4/18/2019	2	Cooler	In hallway adjacent to room E200	Low Right	WF-04182018-011267	12/28/2018	FT-FY19-122018-011267-A	<1	FT-FY19-122018-011267-B	<1
WS-011276	4/18/2018	4/18/2019	3	Cooler	In hallway adjacent to stairwell C1	High Left	WF-04182018-011276	12/28/2018	FT-FY19-122018-011276-A	<1	FT-FY19-122018-011276-B	<1
WS-011277	4/18/2018	4/18/2019	3	Cooler	In hallway adjacent to stairwell C1	Low Right	WF-04182018-011277	12/28/2018	FT-FY19-122018-011277-A	<1	FT-FY19-122018-011277-B	<1
WS-011278	4/18/2018	4/18/2019	3	Cooler	In hallway adjacent to room W300	High Left	WF-04182018-011278	12/28/2018	FT-FY19-122018-011278-A	<1	FT-FY19-122018-011278-B	<1
WS-011279	4/18/2018	4/18/2019	3	Cooler	In hallway adjacent to room W300	Low Right	WF-04182018-011279	12/28/2018	FT-FY19-122018-011279-A	<1	FT-FY19-122018-011279-B	<1
WS-011496	8/17/2018	8/17/2019	Ground Floor	Cooler	In annex adjacent to COT 8	High Left	WF-08172018-011496	12/28/2018	FT-FY19-122018-011496-A	<1	FT-FY19-122018-011496-B	<1
WS-011497	8/17/2018	8/17/2019	Ground Floor	Cooler	In annex adjacent to COT 8	Low Right	WF-08172018-011497	12/28/2018	FT-FY19-122018-011497-A	<1	FT-FY19-122018-011497-B	<1
WS-011498	8/17/2018	8/17/2019	Ground Floor	Cooler	In annex across from COT 9	High Left	WF-08172018-011498	12/28/2018	FT-FY19-122018-011498-A	<1	FT-FY19-122018-011498-B	<1
WS-011499	8/17/2018	8/17/2019	Ground Floor	Cooler	In annex across from COT 9	Low Right	WF-08172018-011499	12/28/2018	FT-FY19-122018-011499-A	<1	FT-FY19-122018-011499-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-010535	Ground Floor	Food Prep Sink	In kitchen on west wall	12/28/2018	FT-FY19-122018-010535-A	<1	FT-FY19-122018-010535-B	<1