



# Deanwood RC Lead Water Test Results



## FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005337	6/3/17	6/3/18	1	Cooler	In hallway adjacent to room 1105 High	WF-62017-005337	2/21/18	FT-FY18--62017-005337-A	<1	FT-FY18--62017-005337-B	<1
WS- 005340	6/3/17	6/3/18	1	Cooler	In hallway adjacent to room 1505 Left High	WF-62017-005340	2/21/18	FT-FY18--62017-005340-A	<1	FT-FY18--62017-005340-B	<1
WS- 005347	6/3/17	6/3/18	1	Fountain	In classroom 1410 in restroom area third clockwise around room from entry door Right	WF-62017-005347	2/21/18	FT-FY18--62017-005347-A	<1	FT-FY18--62017-005347-B	<1
WS- 005358	6/3/17	6/3/18	1	Fountain	In classroom 1414 in restroom area second clockwise	WF-62017-005358	2/21/18	FT-FY18--62017-005358-A	<1	FT-FY18--62017-005358-B	<1

## Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005367	6/3/17	6/3/18	1	Food Prep Sink	In kitchen 1417	WF-62017-005367	2/21/18	FT-FY18--62017-005367-A	<1	FT-FY18--62017-005367-B	<1