



Dorothy Height ES Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 008545	5/8/2019	5/8/2020	1	Cooler	In hallway adjacent to 104	High Left	WF-05082019-008545	11/18/2019	FT-FY20-112019-008545-A	<1	FT-FY20-112019-008545-B	<1
WS- 008546	5/8/2019	5/8/2020	1	Cooler	In hallway adjacent to 104	Low Right	WF-05082019-008546	11/18/2019	FT-FY20-112019-008546-A	<1	FT-FY20-112019-008546-B	<1
WS- 008550	5/8/2019	5/8/2020	2	Cooler	In hallway adjacent to room 212	Low Right	WF-05082019-008550	11/18/2019	FT-FY20-112019-008550-A	<1	FT-FY20-112019-008550-B	<1
WS- 008553	5/8/2019	5/8/2020	3	Cooler	In hallway adjacent to room 310	High Left	WF-05082019-008553	11/18/2019	FT-FY20-112019-008553-A	<1	FT-FY20-112019-008553-B	<1
WS- 008554	5/8/2019	5/8/2020	3	Cooler	In hallway adjacent to room 310	Low Right	WF-05082019-008554	11/18/2019	FT-FY20-112019-008554-A	<1	FT-FY20-112019-008554-B	<1
WS- 008555	9/25/2019	9/25/2020	1	Classroom Faucet	Annex, in classroom 013		WF-09252019-008555	11/18/2019	FT-FY20-112019-008555-A	<1	FT-FY20-112019-008555-B	<1
WS- 008556	9/25/2019	9/25/2020	1	Classroom Faucet	Annex, in classroom 015		WF-09252019-008556	11/18/2019	FT-FY20-112019-008556-A	1.1	FT-FY20-112019-008556-B	<1
WS- 008557	9/25/2019	9/25/2020	1	Classroom Faucet	Annex, in classroom 017		WF-09252019-008557	11/18/2019	FT-FY20-112019-008557-A	<1	FT-FY20-112019-008557-B	<1
WS- 008558	5/8/2019	5/8/2020	1	Break Room	Annex, in staff lounge 009		WF-05082019-008558	11/18/2019	FT-FY20-112019-008558-A	<1	FT-FY20-112019-008558-B	<1
WS- 008560	9/25/2019	9/25/2020	1	Classroom Faucet	Annex, in classroom 016		WF-09252019-008560	11/18/2019	FT-FY20-112019-008560-A	1.7	FT-FY20-112019-008560-B	<1
WS- 008561	9/25/2019	9/25/2020	1	Classroom Faucet	Annex, in classroom 014		WF-09252019-008561	11/18/2019	FT-FY20-112019-008561-A	<1	FT-FY20-112019-008561-B	<1
WS- 008590	9/25/2019	9/25/2020	1	Classroom Faucet	Annex, in classroom 007 west wall		WF-09252019-008590	11/18/2019	FT-FY20-112019-008590-A	2.6	FT-FY20-112019-008590-B	<1
WS- 008591	5/8/2019	5/8/2020	1	Cooler	Annex, in classroom 007		WF-05082019-008591	11/18/2019	FT-FY20-112019-008591-A	<1	FT-FY20-112019-008591-B	<1
WS- 008592	9/25/2019	9/25/2020	1	Classroom Faucet	Annex, in classroom 012		WF-09252019-008592	11/18/2019	FT-FY20-112019-008592-A	<1	FT-FY20-112019-008592-B	<1
WS- 010543	9/25/2019	9/25/2020	1	Classroom Faucet	Annex, in classroom 006		WF-09252019-010543	11/18/2019	FT-FY20-112019-010543-A	<1	FT-FY20-112019-010543-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 008541	7/2/2019	7/2/2020	1	Food Prep Sink	In kitchen	Left	WF-07022019-008541	11/18/2019	FT-FY20-112019-008541-A	<1	FT-FY20-112019-008541-B	<1