



DOROTHY HEIGHTS (BURDICK) LEAD WATER TEST RESULTS May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	BURDICK	5/10/2016	WS- 008540	Utility	Basement	In boiler room sink (water source)	WT-042916-8557- A	9.7	WT-042916-8557- B	2.6			
2	BURDICK	5/10/2016	WS- 008541	Kitchen	1	In kitchen Left	WT-042916-8558- A	1.1	WT-042916-8558- B	< 1			
3	BURDICK	5/10/2016	WS- 008542	Kitchen	1	In kitchen Mid	WT-042916-8559- A	< 1	WT-042916-8559- B	< 1			
4	BURDICK	5/10/2016	WS- 008543	Kitchen	1	In kitchen Right	WT-042916-8560- A	1.7	WT-042916-8560- B	< 1			
5	BURDICK	5/10/2016	WS- 008544	Classroom	1	In classroom 103	WT-042916-8561- A	< 1	WT-042916-8561- B	< 1			
6	BURDICK	5/10/2016	WS- 008545	Cooler	1	In hallway adjacent to 103 Left High	WT-042916-8562- A	< 1	WT-042916-8562- B	< 1			
7	BURDICK	5/10/2016	WS- 008546	Cooler	1	In hallway adjacent to 103 Right Low	WT-042916-8563- A	< 1	WT-042916-8563- B	< 1			
8	BURDICK	5/10/2016	WS- 008547	Classroom	1	In room 106A	WT-042916-8564- A	< 1	WT-042916-8564- B	< 1			
9	BURDICK	5/10/2016	WS- 008548	Health Suite	1	In room 116	WT-042916-8565- A	< 1	WT-042916-8565- B	< 1			
10	BURDICK	5/10/2016	WS- 008549	Cooler	2	In hallway adjacent to room 219 Left High	WT-042916-8566- A	< 1	WT-042916-8566- B	< 1			
11	BURDICK	5/10/2016	WS- 008550	Cooler	2	In hallway adjacent to room 219 Right Low	WT-042916-8567- A	3.6	WT-042916-8567- B	< 1			
12	BURDICK	5/10/2016	WS- 008551	Classroom	2	In room 221	WT-042916-8568- A	11.8	WT-042916-8568- B	2.1			
13	BURDICK	5/10/2016	WS- 008552	Classroom	2	In room 215	WT-042916-8569- A	9.4	WT-042916-8569- B	< 1			
14	BURDICK	5/10/2016	WS- 008553	Cooler	3	In hallway adjacent to 310 Left High	WT-042916-8570- A	< 1	WT-042916-8570- B	< 1			
15	BURDICK	5/10/2016	WS- 008554	Cooler	3	In hallway adjacent to room 310 Right Low	WT-042916-8571- A	< 1	WT-042916-8571- B	< 1			
16	BURDICK	5/10/2016	WS- 008555	Classroom	1	Annex, in room A13	WT-042916-8572- A	< 1	WT-042916-8572- B	< 1			
17	BURDICK	5/10/2016	WS- 008556	Classroom	1	Annex in room 15	WT-042916-8573- A	< 1	WT-042916-8573- B	< 1			
18	BURDICK	5/10/2016	WS- 008557	Classroom	1	Annex, in room A17	WT-042916-8574- A	< 1	WT-042916-8574- B	< 1			
19	BURDICK	5/10/2016	WS- 008558	Classroom	1	Annex in room A9	WT-042916-8575- A	< 1	WT-042916-8575- B	< 1			
20	BURDICK	5/10/2016	WS- 008559	Cooler	1	Annex, in hallway adjacent to room 12	WT-042916-8576- A	< 1	WT-042916-8576- B	< 1			
21	BURDICK	5/10/2016	WS- 008560	Classroom	1	Annex in room 16	WT-042916-8577- A	1.7	WT-042916-8577- B	< 1			
22	BURDICK	5/10/2016	WS- 008561	Classroom	1	Annex room 14	WT-042916-8578- A	< 1	WT-042916-8578- B	< 1			
23	BURDICK	5/10/2016	WS- 008589	Classroom	1	Annex, in room 7 north wall	WT-042916-8606- A	1.9	WT-042916-8606- B	< 1			
24	BURDICK	5/10/2016	WS- 008590	Classroom	1	Annex, in room 7 S wall	WT-042916-8607- A	4.1	WT-042916-8607- B	< 1			
25	BURDICK	5/10/2016	WS- 008592	Classroom	1	Annex, in room 12	WT-042916-8609- A	6.1	WT-042916-8609- B	4.1			

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.